

47166^a

Report of Survey for Repairs, &c., of Engines & Boilers.

No. _____ Port of London (Received at London Office, _____)
No. in Survey held at London Date, first Survey 21 March Last Survey 19 April 1887
Reg. Book. 382 on the Machinery of the S. S. Windermere (Number of Visits 3 Year Month)
Tonnage, Gross 6457 Built at London When built 1857 - -
Ditto, Net 399 Owners Allan & Co Port belonging to London
Diameter of Cylinder 23.41 Engines made by J. Penn & Sons When made 1878
Length of Stroke 24 Boilers made by " When made 1878
Pressure of Steam 58 If Surveyed Afloat or in Dry Dock (State Name of Dock.)
Registered Horse Power 80 Classed A 1
Last Survey No. _____ Port L.N.E. 1.86

Particulars of Repairs and Examination Annual survey
(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Main boiler examined inside & found in fair condition, bad part in furnace sides & bottoms cut out & patches fitted: new doubling plate on mud hole door. Tubes cut out in wings & plugs fitted with tube plates & stays where necessary.

Safety valves examined.
Donkey boiler in fair condition - no repairs.
Fitted main boiler to 120 lb & donkey boiler to 60 lb.
The main safety valves were found to blow off at 60 lb.

General Observations, Opinion, and Recommendation:-- The machinery of this vessel
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)
as far as seen, is now in good order & eligible in our opinion to remain as classed with the record B.S. 487 in the Register Book.

Office or Registration Fee (per Sec. 27)..... £ : :
Survey Fee (per Section 28) £ 2 : 2
Special on Damage, Fee (per Section 28) £ : 2 : 6
*Certificate (if required) to be sent as per margin.. £ : :
Travelling Expenses (if chargeable)..... £ : :
received by me, 9/5/87 1887
John Walker & Co. Surveyors
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUESDAY 3 MAY, 1887
Assigned B.S. 4, 87

It is submitted that this vessel
is eligible to have the notification
B S 4.87 recorded the boilers
being subject to survey as
per Rule.

D.F.
27/4/87



© 2021

Lloyd's Register
Foundation