

REPORT of SURVEY for REPAIRS, &c.

47466 47426

Received in London Office, JULY 22 JULY 1887

Port of London

Survey held at Linehouse Date, First Survey 2 July Last Survey 25 July 1887

on the M.S. "Miranda" Master A Keys

TONNAGE:— 736 Built at Newcastle By whom Palmer's Co When 1865 3

Owners J. Fenwick & Son Port belonging to London

Owner's Address (if not already recorded in Appendix to Register Book.)
 Name of Dock Linekiln Destined Voyage Italy

Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Qr. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 46882 Port Lon Classed SS Lon No 3.81 SS Lon No 1.84

REPAIRS, OR EXAMINATION AS PER RULE, FOR SS No 2

Bottom Examined good. Tanks/ballast/ cleaned out and examined and afterwards tested. - Cement repaired. - Hold cleaned and painted. Forecastle frames varnished. Cabin linings renewed. The plating & frames cleaned and painted. Forepecks cleaned and painted. 3 planks of Quarter Deck renewed with Yellow Pine. Bottom repainted. Masts Examined - Chain Cables raised on last special survey (1884)

PRESENT CONDITION OF THE	<u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>	<u>3hs</u>	<u>Good</u>
Decks	<u>Good</u>	Keel (Bottom) & Counter	<u>Good</u>	Ceiling	<u>Good</u>	Boats
Waterways	<u>---</u>	Trunnions or Rivets	<u>---</u>	Rudder	<u>---</u>	Masts, Yards, &c.
Comings	<u>---</u>	Breasthooks and Stemson	<u>---</u>	Windlass & Capstan	<u>---</u>	Condition, how ascertained
Up'r Dk. Beams & Fastenings	<u>---</u>	Transoms, Pointers, & Crutches	<u>---</u>	Pumps	<u>4hs</u>	Sails
Low'r Dk. Beams & Fastenings	<u>---</u>	Timbers of Frame at the openings	<u>---</u>	Cement (if Iron Ship)	<u>---</u>	Anchors No. of <u>3 B. 15 + 2 K</u>
Planksheers	<u>---</u>	Ditto ditto at other places	<u>---</u>	Caulking of Bot'm, D'k, & Watrways	<u>---</u>	Cables <u>part seen</u>
Sheerstrakes	<u>---</u>	Keelsons	<u>---</u>	Copper, or Y.M. (State if on Felt.)	<u>---</u>	Hawsers & Warps <u>6hs</u>
Topsides	<u>---</u>	Clamps & Shelves	<u>---</u>	When put on	<u>---</u>	Standing & Running Rigging
Wales	<u>---</u>	Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	Cargo & Main Hatchways
Engine Room Skylights	<u>Good</u>					Hatches

General Observations, Opinion as to Class, Recommendation, &c. :
She is now in good condition and in my opinion eligible to continue as classed and B.S. No 2 as recorded in the Register Book

	£	s	d
Entry Fee (if chargeable) per Scale I., Sec. 27...			
Office Fee (if chargeable) per Scale II., Sec. 27...			
Survey Fee (per Section 28)	4	4	
Special on Damage, Fee (if any) (per Sec. 28)....			
*Certificate (if required) to be sent as per margin			
Travelling Expenses (if chargeable)			
Second Surveyor's Fee (if any)			
Fees received by me, 3-8-1887			

Wm. B. Davey
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____
 Character assigned SS No 2
13 M.S. 7/87

The Surveyors are requested not to write on or below

Insert Character precisely as in Register Book

L 01680-0457