

REPORT of SURVEY for REPAIRS, &c.

4485-4785

No. 1116 Port of London Received in London Office, 10/12/87
 No. in Reg. Book. 1116 Survey held at on the S.S. "Assyrian Monarch" Date, First Survey 1880 Last Survey 1887
(No. of Visits)

Master W. S. Main - 87
YEAR. MONTH.
 TONNAGE - NET 2608 Built at Kull By whom Earliest When 1880
 GROSS 3970 Owners J & A Allan Port belonging to Glasgow
 UNDER DK. 1996 Owner's Address Glasgow
(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Name of Dock Glasgow Destined Voyage Glasgow
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
(if these particulars are not yet recorded in the Register Book.) Years assigned, if a Wood Ship. Character in Register Book.

Last Survey, No. 1115 Port London Classed 100A1
S.S. No. 1-85 10/86

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in salt water ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in fresh water ft. ins.
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE
Messrs. Allan Bros & Co state in their letter of the 6th August 1887 that Messrs J & A Allan the new owners, do not intend to continue this vessel in the Register Book.

PRESENT CONDITION OF THE	Plank (Bottom) & Counter	Ceiling	Boats
Decks	Treenails or Rivets	Rudder	Masts, Yards, &c.
Waterways	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Comings	Transoms, Pointers, & Crutches	Pumps	Sails
Up'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (If Iron Ship)	Anchors No. of
Low'r Dk. Beams & Fastenings	Ditto ditto at other places	Caulk'ng of Bot'm, D'k, & Wat'rways	Cables
Planksheers	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Sheerstrakes	Clamps & Shelves	When put on	Standing & Running Rigging
Popsides			
Vales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, &c. :

Reported by G.C. 11/8/87

Confirmed by G.C. 9/10/87

Entry-Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	} received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute TUESDAY 9 AUGUST 1887

Character assigned Withdrawn Class
and issued three days
13/10/87

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

If Ship, state whether or not a Repair is also sent on the Machinery

Insert Character precisely as in Register Book.

8470-089207