

44594  
**REPORT of SURVEY for REPAIRS, &c.**

No. 44594

Port of London

Received in London Office, **WEDNES. 14 SEPT 1887**

No. in  
Reg. Book.

Survey held at

London

Date, First Survey 10<sup>th</sup> Sept

Last Survey 13<sup>th</sup> Sept 1887

31' on the Iron Barque "Unguento"

Master *Samuel*  
YEAR. MONTH.

TONNAGE:—

NET 280

GROSS 304

UNDER DK. 245

Built at Sunderland

By whom W. Pile & Co

When 1871

Owners Bullard King & Co

Port belonging to London

Owner's Address  
(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Name of Dock Horseferry Destined Voyage Natal

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.  
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 20. Port FIVE

Classed

1.1. Lon. No. 3.85

100 A1

5-85

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition

The bottom outside is in good order, it has been cleaned coated. The rudder pintles have been relubricated.

PRESENT CONDITION OF THE

Decks	Good	Planks (Bottom) & Counter	Good	Ceiling	Good	Boats	Good
Waterways	"	Tranoms or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks and stemson	"	Windlass & Capstan	"	Condition, how ascertained	from deck
Up'r Dk. Beams & Fastenings	"	Transoms, Painters & Gratches	"	Pumps	"	Sails	Good
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (If Iron Ship)	"	Anchors No. of 3. 1. 2. 3.	Good
Blackboards	"	ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	Port-seen good
Sheerstrakes	"	Keelsons	"	Copper, of Y.M. (State if on Fell.) When put on	"	Hawsers & Warps	Suitable
Topsides	"	Clamps & Shells	"	Scuppers	Good	Standing & Running Rigging	Good
Wales	"			Cargo & Main Hatchways	Good	Hatches	"
Engine Room Skylights	Good	Coal Bunker, Openings, Lids, &c.	Good				

General Observations, Opinion as to Class, Recommendation, &c.:


This vessel now appears to be in a sound and efficient condition eligible in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28) .....	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable) .....	£	:	:	
Second Surveyor's Fee (if any) .....	£	:	:	

Committee's Minute **FRIDAY 13 SEPT 1887**

Character assigned

Allison D. Wilson.  
Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation