

# REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

SAT 24 SEPT 1887

No.

No. in Reg. Book.

Survey held at *London*

Date, First Survey *10<sup>th</sup> Sept* Last Survey *10<sup>th</sup> Sept* 18 *87*

(No. of Visits)

Master

YEAR.

MONTH.

TONNAGE:—

NET *1058*

GROSS *1636*

UNDER DECK *1222*

Built at *Ch. Shields*

By whom *J & W. Smith*

When *1884* *2*

Owners

*Scrutton Sons & Co*

Port belonging to

*London*

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock *Dry Dock* Name of Dock *Greens Dry Dock* Destined Voyage

Length of Poop *11* ft.: of Forecastle *11* ft.: of Raised Or. Deck *11* ft.: Moulded Depth *12* ft. ins.

(If these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No. *1635* Port *Cardiff*

Classed

*100 A1*

*12.86*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship

in salt water

ft. ins.

in fresh water

ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE

*Annual Survey*

*This vessel has now been placed in graving dock, cleaned and recoated and the equipment generally overhauled and made good.*

## PRESENT CONDITION OF THE

Decks <i>good</i>	Plank (Bottom) & Counter <i>good</i>	Ceiling <i>good</i>	Boats <i>complete &amp; good</i>
Waterways <i>"</i>	Trunnels or Rivets <i>"</i>	Rudder <i>"</i>	Masts, Yards, &c. <i>"</i>
Comings <i>"</i>	Breasthooks and Stemson <i>"</i>	Windlass & Capstan <i>"</i>	Condition, how ascertained <i>From deck</i>
Up'r Dk. Beams & Fastenings <i>"</i>	Transoms, Pointers, & Crutches <i>"</i>	Pumps <i>"</i>	Sails <i>complete &amp; good</i>
Low'r Dk. Beams & Fastenings <i>"</i>	Timbers of Frame at the openings <i>"</i>	Cement (If Iron Ship) <i>"</i>	Anchors No. of <i>3 B 15 2K</i>
Planksheers <i>"</i>	Ditto ditto at other places <i>"</i>	Caulking of Bot'm, D'k, & Watrways <i>"</i>	Cables <i>Complete, not ranged</i>
Sheerstrakes <i>"</i>	Keelsons <i>"</i>	Copper, or Y.M. (State if on Felt.) <i>"</i>	Hawsers & Warps <i>"</i>
Topsides <i>"</i>	Clamps & Shelves <i>"</i>	When put on <i>"</i>	Standing & Running Rigging <i>1 &amp; good</i>
Engine Room Skylights <i>"</i>	Coal Bunker, Openings, Lids, &c. <i>"</i>	Scuppers <i>good</i>	Cargo & Main Hatchways <i>good</i>
Hatches <i>"</i>			

General Observations, Opinion as to Class, &c.:

*This vessel is in good condition and eligible in our opinion to remain as classed*

Entry Fee (if chargeable) per Scale I., Sec. 27.

Office Fee (if chargeable) per Scale II., Sec. 27.

Survey Fee (per Section 28)

Special Damage Fee (if any) (per Sec. 28)

\*Certificate (if required). See margin.

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

received by me, 188

Committee's Minute

TUESDAY 4 OCT 1887

Character assigned

Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register Foundation