

47662
REPORT of SURVEY for REPAIRS, &c.

Port of London

Received in London Office MONDAY 22 AUGUST 1887

No. in Reg. Book. Survey held at London Date, First Survey 15th Augst Last Survey 17th Augst 1887

1095 on the S.S. "Congella". Master Cringle

TONNAGE:— Built at Sunderland By whom W. D. or find & sons When 1851

NET 1041 Owners Bullard King & Co. Port belonging to London

GROSS 1597 Owner's Address (if not already recorded in Appendix to Register Book.)

UNDER DECK 1560 If Surveyed Afloat or in Dry Dock Dry Name of Dock Regent Destined Voyage Cardiff

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins. Years assigned, if a Wood Ship. Character in Register Book.

Classed 100 A1 4-87

Last Survey, No. 47/143 Port London S.S. No 386

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.) Society's Freeboard (if assigned) as painted on Ship in Summer ft. ins. in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

The bottom outside is in good order. It has been cleaned and coated.

The rudder has been overhauled and the painter rubbed.