

REPORT of SURVEY for REPAIRS, &c.

No. 399 Date of Writing Report 188 Port of London Received in London Office, WEDNES 28 OCT 1887

No. in Reg. Book. 399 Survey held at London Date, First Survey 13th Oct Last Survey 15th Oct 1887

TONNAGE: NET 1359 GROSS 1359 UNDER DECK 1195 On the Iron Ship "Winefred" Master E. E. E. Built at Chester By whom E. Crami When 1855 Owners Taylor Sons & Co. Port belonging to London

If Surveyed Afloat or in Dry Dock Dry Name of Dock West India Destined Voyage Length of Poop ft. of Forecastle ft. of Raised Or. Deck ft. Moulded Depth ft. ins. Last Survey, No. 46729 Port

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition. The bottom outside is in good order, it has been cleaned and coated.

Table with 4 columns: Decks, Plank (Bottom) & Counter, Ceiling, Boats. Rows include Waterways, Comings, Up'r Dk. Beams & Fastenings, Low'r Dk. Beams & Fastenings, Sheerstrakes, Topsides, Engine Room Skylights, Coal Bunker, Openings, Lids, &c., Scuppers, Cargo & Main Hatchways, Hatches.

General Observations, Opinion as to Class, Recommendation, &c.: This vessel now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed

Table with 2 columns: Fees applied for, Received by me. Rows include Entry Fee, Office Fee, Survey Fee, Special on Damage, Travelling Expenses, Second Surveyor's Fee.

Committee's Minute Character assigned FRIDAY 28 OCT 1887 Allison B. Wilson. Surveyor to Lloyd's Register of British & Foreign Shipping.