

REPORT of SURVEY for REPAIRS, &c.

47767

Received in London Office,

TUESDAY 18 OCT 1887

No. in g. Book. 29th on the S.S. Merionethshire

Survey held at London

Date, First Survey 13th Oct^r Last Survey 13th Oct^r 1887th

(No. of Visits)

Master

YEAR.

MONTH.

TONNAGE:—

NET 1245

GROSS 1907

UNDER DK. 1817

Built at Glasgow

Owners Leith H^c

By whom Lon & Glas. C.

When 1878

4

Port belonging to London

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock R. Alth

Destined Voyage Hamburg.

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck

ft.: Moulded Depth ft. ins.

Years assigned, if a Wood Ship.

Character in Register Book.

Classed

Last Survey, No. 1301 Port Ant

S.S. Ham. No 1-84

100 A1

4.87

State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE Part S.S. No 2

See Antwerp Report No 1201 8th April 1887

The vessel has now been placed in dry dock & the bottom cleaned and recoated.

The Cross bunkers and the Engine & boiler space have also been cleared - the wood ceiling taken up & the iron surfaces scaled & recoated. The cement here was found to be good.

Masts & spars examined & found good.

Other parts of the vessel are to be examined under the requirements for this survey at Hamburg - whether the vessel is now fine

PRESENT CONDITION OF THE

Decks	found	Plank (Bottom) & Counter	found	Ceiling	found	Boats	
Waterways	"	Treenails or Rivets	"	Rudder	found	Masts, Yards, &c.	found
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	certified
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors No. of	
Planksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	
Sheerstrakes	"	Keelsons	"	Copper, or P.M. (State if on Pett.)	"	Hawsers & Warps	
Topsides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	found
Wales	"		"		"	Hatches	found
Engine Room Skylights	found	Coal Bunker, Openings, Lids, &c.	found	Scuppers	found	Cargo & Main Hatchways	found
General Observations, Opinion as to Class, &c.:							

As noted above - this survey will be completed at Hamburg

Entry Fee (if chargeable) per Scale I., Sec. 27. £
Office Fee (if chargeable) per Scale II., Sec. 27. £
Survey Fee (per Section 28) £ 1 1 0
Special Damage Fee (if any) (per Sec. 28) £
Certificate (if required). See margin. £
Travelling Expenses (if chargeable) £
Surveyor's Fee (if any) £ 10 6

received by me,

14.12.1887

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRIDAY 4 NOV 1887 TUESDAY 15 NOV 1887