

# REPORT of SURVEY for REPAIRS, &c.

47854

Date of Writing Report 25-11-87 1887 Port of London Received in London Office, MONDAY 28 NOV 1887

Survey held at London Date, First Survey 21-11-87 Last Survey 26-11-1887

on the Holmside Iron Ship Master Searge

NAME:— 515 Built at S. Shields By whom Leadhead & Co When 1871

814 Owners A. P. Harrison & Co Port belonging to London

738 Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Union Dock Destined Voyage Tyne

ft. of Poop \_\_\_\_\_ ft. of Forecastle \_\_\_\_\_ ft. of Raised Or. Deck \_\_\_\_\_ ft. of Moulded Depth \_\_\_\_\_ ft. ins. Character in Register Book.

Classed GOA1

Survey, No. \_\_\_\_\_ Port \_\_\_\_\_

Clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer \_\_\_\_\_ ft. ins. as painted on Ship in Winter \_\_\_\_\_ ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR \_\_\_\_\_

Condition

This vessel was placed in dry dock, the bottom examined cleaned & coated where necessary. Several rivets renewed in Engine Room at the fore end of the space and at aft end of fore Yank. The cement on them replaced.

PRESENT CONDITION OF THE	Plank (Bottom) & Counter	Ceiling	Boats
<u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>
Decks	Treenails or Rivets	Rudder	Masts, Yards, &c.
Deckways	Breasthooks & Stems	Windlass & Capstan	Condition, how ascertained
Stowings	Transoms, Pointers, & Crutches	Pumps	Sails
Fore Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. <u>310, 13, 20</u>
Aft Dk. Beams & Fastenings	Ditto ditto at other places	Caulking of Bot'm, D'k, & Wat'rways	Cables <u>what can be</u>
Keelsons	Keelsons	Copper, or Y.M. (State if on Felt.) When put on	Hawsers & Warps
Deerstrakes	Clamps & Shelves	Scuppers <u>Good</u>	Standing & Running Rigging
Spikes	Coal Bunker, Openings, Lids, &c.	Cargo & Main Hatchways <u>Good</u>	Hatches
Staircases			
Engine Room Skylights			

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel now appears to be in a sound and efficient condition & in my opinion to remain as classed.

Entry Fee (if chargeable) per Scale I, Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II, Sec. 27...	£	:	:
Survey Fee (per Section 28) .....	£	1	1
Special on Damage, Fee (if any) (per Sec. 28) .....	£	:	:
Certificate (if required) to be sent as per margin	£	:	5
Travelling Expenses (if chargeable) .....	£	:	:
Second Surveyor's Fee (if any) .....	£	:	:

Fees applied for, 5.12.1887  
 Received by me, Edward J. M. Surveyor  
 10.12.1887  
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUESDAY 6 DEC 1887  
 Character assigned GOA1