

REPORT of SURVEY for REPAIRS, &c.

48159

Received in London Office, WEDNES. 7 MARCH 1888

No. Date of Writing Report 188 Port of
 No. in Survey held at London Date, First Survey 15 Febry. Last Survey 1st March 1888.
 eg. Book. (No. of Visits)

625 on the S.S. Envoy Master Mugent
 TONNAGE:— Built at Hull By whom Robert Hooper When 1842 /
 NET 881 Owners H. S. Bailey Port belonging to Hull
 GROSS 1353 Owner's Address YEAR. MONTH.

UNDER DK. 1059 (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Afloat Name of Dock Mullwall St Destined Voyage
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 2671 Port South Classified SS No 3. 84
 State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer 90 A 1 ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter 5.84 ft. ins.
 of any letters respecting this case.

PAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Survey
See Southampton Report No 2671

The after peak has now been filled with water & the peak bulkhead tested & found satisfactory
 A steel wire 3 1/2 in rope has now been supplied

PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the opening	Cement (if Iron Ship)	Anchors No. of
Flanksheers	Ditto ditto at other places	Caulk'ng of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :

This vessel appears to be in good condition: Survey, in this instance, has however been confined to the matters stated above.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 188 Received by me, 188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)...	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Robert Hooper
 Surveyor to Lloyd's Register of British & Foreign Shipping

FRIDAY, 8 MARCH 1888
 90 A 1 12/87

Committee's Minute
 Character assigned

Insert Character precisely as in Register Book.