

48854

# REPORT of SURVEY for REPAIRS, &c.

No. *46* Date of Writing Report *Oct 1883* 188*3* Port of *London*  
No. in Reg. Book. *46* Survey held at *London* Date, First Survey *Don Low* No. of Visits *1* Master *Smith* Last Survey *Oct 1883* 188*3*  
TONNAGE:— NET *462* GROSS *217* UNDER DK. *553*  
Built at *Liverpool* By whom *Trustman & Co* When *1882* — *10*  
Owners *a Marshall* Port belonging to *Aberdeen*  
Owners' Address *(if not already recorded in Appendix to Register Book.)*  
If Surveyed Afloat or in Dry Dock *Afloat* Name of Dock *Northfleet* Destined Voyage *Shields*  
Length of Poop *ft.:* of Forecastle *ft.:* of Raised Or. Deck *ft.:* Moulded Depth *ft.:* ins. *100 4 1*  
*(if these particulars are not yet recorded in the Register Book.)* Years assigned, if a Wood Ship. Character in Register Book. *6-87*  
Classed *100 4 1*  
Last Survey, No. *20449* Port *Inver Sh*  
*(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)*  
REPAIRS, OR EXAMINATION AS PER RULE, FOR *Condition*

This vessel was seen lying afloat in the River off Brighton Wharf, Northfleet.  
It was observed that a 2<sup>nd</sup> cut keel was required and that the wheel chains are worn. It appears that the vessel will be dry docked at Shields where the vessel will be submitted for survey.

PRESENT CONDITION OF THE			
Decks	<i>Good</i>	Plank (Bottom) & Counter	<i>Good</i>
Waterways	"	Treenails or Rivets	"
Comings	"	Breasthooks & Stemson	"
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"
Planksheers	"	Ditto ditto at other places	"
Sheerstrakes	"	Keelsons	"
Topsides	"	Clamps & Shelves	"
Wales	"		
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"
		Scuppers	<i>Good</i>
		Cargo & Main Hatchways	<i>Good</i>
		Hatches	"
		Boats	<i>Good</i>
		Masts, Yards, &c.	"
		Condition, how ascertained	<i>from 12</i>
		Sails	<i>Good</i>
		Anchors	No. of <i>33, 18, 11</i>
		Cables	<i>Good</i>
		Hawsers & Warps	"
		Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel will be submitted for survey at Shields dry dock & suggest that the Society's Surveyor at that port be advised.


Entry Fee (if chargeable) per Scale I., Sec. 27...	£	
Office Fee (if chargeable) per Scale II., Sec. 27...	£	
Survey Fee (per Section 28) .....	£	
Special on Damage, Fee (if any) (per Sec. 28) ....	£	
*Certificate (if required) to be sent as per margin	£	
Travelling Expenses (if chargeable) .....	£	
Second Surveyor's Fee (if any) .....	£	

Fees applied for, 188  
Received by me, 188

*Edward J. M. M. M.*  
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute  
Character assigned

TUES 30 OCT 1883



Lloyd's Register  
Foundation  
LON 684-0161