

REPORT of SURVEY for REPAIRS, &c.

48943

Received in London Office,

20. 11. 88

No. 405 Date of Writing Report Nov 193 1888 Port of London
 No. in Reg. Book 405 Survey held at London Date, First Survey 7 Last Survey Nov 193 1888
 on the Pleides Iron S. Master Seton

TONNAGE:—
 NET 997 Built at Dumbarton By whom Mc Millan & Co When 1869-9
 GROSS 1020 Owners Shaw Savill & Albion Coy Port belonging to Southampton
 UNDER DK. 935 Owners' Address (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Afloat Name of Dock East India S. Destined Voyage Duckland
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 47928 Port Lon Classed SS Nov-84 Character in Register Book *A
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter ft. ins.
 of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR
Marking Freeboard
 The freeboard assigned by the Committee of this Society has been marked & painted upon the sides of the vessel as directed viz.—
 Sides 3-11
 Bow 3-6 1/2

Edward J. Turner


PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulk'ng of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 188
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	Received by me, 188
Second Surveyor's Fee (if any)	£	:	:	

96

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
 LONG 847-0289

Form No. 2 for Repairs—1000—12/9/88.—Transfer Ink.—T. & S.
 The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.