

REPORT of SURVEY for REPAIRS, &c.

No. 800 Date of Writing Report 188 Port of London Date, First Survey 22<sup>nd</sup> Feb Last Survey 22<sup>nd</sup> Feb 1889

Survey held at London on the S.S. "Miranda" TONNAGE: NET 593 736 GROSS 948 296 UNDER DEK. 855 Built at Newcastle By whom Palmer & Co. Owners J. Fenwick & Co. When 1865 3 Port belonging to London

If Surveyed Afloat or in Dry Dock On Dry Name of Dock Limekiln Destined Voyage Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins. Years assigned, if a Wood Ship. Character in Register Book. Last Survey, No. 4873 Port Lon S.S. No. 3. 2. 81 S.S. Lon. No 2-87

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition This vessel has now been placed in dry dock bottom cleaned & coated with tallow.

PRESENT CONDITION OF THE			
Decks	gnd	Plank (Bottom) & Counter	gnd
Waterways	"	Transverse Rivets	pt cen
Comings	"	Breasthooks and Stemson	mt cen
Up'r Dk. Beams & Fastenings	pt cen	Transoms, Pointers, & Crutches	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	gnd
Planksheers	"	Ditto ditto at other places	"
Sheerstrakes	Rating	Keelsons	pt cen
Topsides	"	Clamps & Shelves	"
Wales	"		
Engine Room Skylights	gnd	Coal Bunker, Openings, Lids, &c.	gnd
General Observations, Opinion as to Class, Recommendation, &c.:		Scuppers	gnd
		Cargo & Main Hatchways	gnd
		Hatches	"

This vessel appears to be in good condition & eligible to my opinion to remain as classed

Entry Fee (if chargeable) per Scale I., Sec. 27... £ : : Office Fee (if chargeable) per Scale II., Sec. 27... £ : : Survey Fee (per Section 28) £ : : Special on Damage, Fee (if any) (per Sec. 24) £ : : \*Certificate (if required) to be sent as per margin £ : : Travelling Expenses (if chargeable) £ : : Second Surveyor's Fee (if any) £ : : Fees applied for, 188 Received by me, 188 Committee's Minute FRIDAY 1 MARCH 1889 Character assigned 80 A

Surveyor to Lloyd's Register of British & Foreign Shipping. Lloyd's Register Foundation LON 685-0168