

REPORT of SURVEY for REPAIRS, &c.

49691

FRIDAY 19 JULY 1889

No. 1889 Port of London
Survey held at London
Date, First Survey June 13 Last Survey July 13 1889
On the Lady Penrhyn
Built at Glasgow
By whom A. Deplens
Master Thomas
Tonnage: NET 875 GROSS 839 UNDER DK. 788
Owners Richards & Coy
Owner's Address
Port belonging to Liverpool
If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Rye Dock
Destined Voyage Aden
Length of Poop ft. of Forecastle ft. of Raised Or. Deck ft. Moulded Depth ft. ins.
Classed 100 A. 1
7-88

Last Survey, No. 3799 Port
REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition
This vessel was placed in dry dock, the bottom and rudder examined cleaned & coated about 300 fat & new 3 1/2 deck fitted & caulked.

PRESENT CONDITION OF THE			
Decks	Good	Plank (Bottom) & Counter	Good
Waterways	"	Treenails or Rivets	"
Comings	"	Breasthooks and Stemson	"
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	"
Planksheers	"	Ditto ditto at other places	"
Sheerstrakes	"	Keelsons	"
Topsides	"	Clamps & Shelves	"
Wales	"	Coal Bunker, Openings, Lids, &c.	"
Engine Room Skylights	"	Scuppers	Good
		Cargo & Main Hatchway	Good
		Hatches	"

General Observations, Opinion as to Class, Recommendation, &c.:
This vessel now appears to be in a sound sufficient condition eligible in my opinion to remain as classed & to have recorded 100 A. 1
1889-7-89

Entry Fee (if chargeable) per Scale I., Sec. 27... £
Office Fee (if chargeable) per Scale II., Sec. 27... £
Survey Fee (per Section 28) £
Special on Damage, Fee (if any) £
*Certificate (if required) to be sent as per margin £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Fees applied for, 188
Received by me, 188

Surveyor to Lloyd's Register of British & Foreign Shipping.
Edward M. Turner

Committee's Minute
Character assigned
TUES 23 JULY 1889
100 A. 1

