

# REPORT of SURVEY for REPAIRS, &c.

49867  
25-9-

No. 242 Date of Writing Report 18 Port of London Received in London Office, 25-9-  
 No. in Reg. Book 242 Survey held at London Date, First Survey 16<sup>th</sup> Sept Last Survey 1889  
 on the S.S. Tigro (No. of Visits           ) Master           

TONNAGE:—  
 NET 584 Built at Dundee By whom Goulay Bros. When 1870 MONTH 11  
 GROSS 955 Owners General Steam Nav. Co. Port belonging to London  
 UNDER DK. 818 Owners' Address             
(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Fletcher Destined Voyage             
 Length of Poop            ft.: of Forecastle            ft.: of Raised Or. Deck            ft.: Moulded Depth            ft. ins.  
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 45022 Port Lon + N.B. 13.83 + L.M. 11.83 Classed 100 A1  
S.S. Dun. No 2-11.83. 3.85

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.  
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case. ) as painted on Ship in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

*I went on board this vessel to make the survey now due but could not do this, as the vessel was not prepared.  
 From what I could see, repairs appeared to be necessary to the deck, & to some of the plating in way of the bulkheads.  
 Having written to the Supt. Engineer (as per attached press copy) a reply, also attached, has been received, & no further survey has been made.*

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Wat'rways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. <small>(State if on Felt.)</small>	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c. :

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 18 Received by me, 18
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28) .....	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28) ....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable) .....	£	:	:	
Second Surveyor's Fee (if any) .....	£	:	:	

*W. J. Cooper*  
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 24 JAN 1890  
 Character assigned           

Insert Character precisely as in Register Book.