

# REPORT of SURVEY for REPAIRS, &c.

50480

No. 1 Date of Writing Report 31-3-90 is Port of London Received in London Office, TUES 1 APRIL 1890  
 No. in Survey held at London Date, First Survey 11-3-90 Last Survey 26/3/1890  
 g. Book. 99 on the Norham Castle Iron 8/8 Master George  
(No. of Visits) YEAR. MONTH.

TONNAGE:— Built at Glasgow By whom Elder Coy When 1883-2  
 NET 2667 Owners De Currie Coy Port belonging to London  
 GROSS 4155  
 UNDER DK 4072 Owner's Address  
(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Green Destined Voyage Cape  
 Length of Poop \_\_\_\_\_ ft.: of Forecastle \_\_\_\_\_ ft.: of Raised Or. Deck \_\_\_\_\_ ft.: Moulded Depth \_\_\_\_\_ ft. ins.  
(if these particulars are not yet recorded in the Register Book.) Years assigned, if a Wood Ship. Character in Register Book.

Last Survey, No. 49875 Port Lon Classed 100A1  
9/89  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship) in Summer \_\_\_\_\_ ft. ins.  
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case. in Winter \_\_\_\_\_ ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition As don Nov-87  
BS 7/89

This vessel was placed in dry dock, the bottom examined cleaned and coated.

PRESENT CONDITION OF THE					
Decks	<u>Good</u>	Planks (Bottom) & Counter	<u>Good</u>	Ceiling	<u>Good</u>
Waterways	✓	Trunnels or Rivets	✓	Rudder	✓
Comings	✓	Breasthooks and Stemson	✓	Windlass & Capstan	✓
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Pumps	✓
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the opening	✓	Cement (if Iron Ship)	✓
Planksheers	✓	ditto ditto at other places	✓	Caulking of Bot'm, D'k, & Watrways	✓
Sheerstrakes	✓	Keelsons	✓	Copper, or Y.M. (State if on Felt.)	✓
Topsides	✓	Clamps & Shelves	✓	When put on	✓
Wales	✓	Coal Bunker, Openings, Lids, &c.	✓	Scuppers	<u>Good</u>
Engine Room Skylights	✓			Cargo & Main Hatchways	<u>Good</u>
				Hatches	✓

General Observations, Opinion as to Class, Recommendation, &c. :  
This vessel now appears to be in a sound & efficient condition eligible in my opinion to remain as classed & survey to be recorded 3/90

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28) .....	£	:	:
Special on Damage, Fee (if any) (per Sec. 28)...	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable) .....	£	:	:
Second Surveyor's Fee (if any) .....	£	:	:

Fees applied for, \_\_\_\_\_  
 Received by me, \_\_\_\_\_  
Edward J. Turner  
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 11 APRIL 1890  
 Character assigned 100A1



The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.