

# REPORT of SURVEY for REPAIRS, &c.

50825  
TUE - 1 JUL 90

No. 100 Date of Writing Report 30/6/90 18 Port of London  
 No. in Reg. Book 82 Survey held at London Date, First Survey 28/6/90 Last Survey 30/6/1890  
100 on the GARTH Castle Don Sew Don Sew Master Broadfoot

TONNAGE :-  
 NET 2381 Built at Glasgow By whom Blair & Coy When 1880-12  
 GROSS 3705 Owners D Currie & Coy Port belonging to London  
 UNDER DEK 3537 Owners' Address \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Green Dyke Destined Voyage Cape  
 Length of Poop \_\_\_\_\_ ft.: of Forecastle \_\_\_\_\_ ft.: of Raised Qr. Deck \_\_\_\_\_ ft.: Moulded Depth \_\_\_\_\_ ft. \_\_\_\_\_ ins.  
 (if these particulars are not yet recorded in the Register Book.)  
 Last Survey, No. 50521 Port Lon M.C. 2/88 in Red M.B. 88 in Red Classed 100A1  
Lon 4/90

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)  
 Society's Freeboard (if assigned) in Summer \_\_\_\_\_ ft. \_\_\_\_\_ ins.  
 as painted on Ship in Winter \_\_\_\_\_ ft. \_\_\_\_\_ ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition S. S. Lon 700/89

This vessel was placed in dry dock, the bottom examined cleaned and coated

PRESENT CONDITION OF THE		Plank (Bottom) & Counter		Ceiling		Boats	
Decks	<u>Good</u>		<u>Good</u>		<u>Good</u>		<u>Good</u>
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"	Condition, how ascertained	<u>from the</u>
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	<u>Good</u>
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchor No.	<u>310, S. 2M</u>
Planksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	<u>Good</u>
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"
Topides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"
Wales	"					Hatches	"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"	Scuppers	<u>Good</u>	Cargo & Main Hatchways	<u>Good</u>

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel now appears to be in a sound and efficient condition eligible in my opinion to remain as classed & Survey recorded Lon 6/90

Entry Fee (if chargeable) per Scale I, Sec. 27...	£	:	:	Fees applied for, 18 Received by me, 18 <u>Lawson &amp; Co Surveyors</u> Surveyor to Lloyd's Register of British & Foreign Shipping.
Office Fee (if chargeable) per Scale II, Sec. 27...	£	:	:	
Survey Fee (per Section 28) .....	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28) ....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable) .....	£	:	:	
Second Surveyor's Fee (if any) .....	£	:	:	

Committee's Minute ✓ FRI 4, JULY 1890  
 Character assigned 100A1

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent.

Insert Character precisely as in Register Book.

