

REPORT of SURVEY for REPAIRS, &c.

Received in London Office, TUES 12 AUGUST 1890

No. 57044 Date of Writing Report 18 Port of London
 No. in Reg. Book. 650 Survey held at S.S. Mona Date, First Survey 31st May Last Survey 7th Aug. 1890.
 (No. of Visits 9) Master

Tonnage:— NET 286 GROSS 491 UNDER DK. 435
 Built at Hull By whom C. W. Parle When 1866 7
 Owners J. B. Scott Port belonging to Hull

Owners' Address (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Afloat Name of Dock Lon + W. Dock Destined Voyage

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 50746 Port London
 Classed B.L.M.S. 10.89 S.S. 11.89
 Character in Register Book 85A1

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)
 Society's Freeboard (if assigned) as painted on Ship in Summer 2 ft. 1 ins. in Winter 2 ft. 2 1/2 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Freeboard Marking to Fresh water 3 in. above disc

The freeboard marking as approved for this vessel have now been put on in accordance with the requirements
 It is stated that on the 30th May 1890 a fire occurred under the bridge deck by which the deck was badly charred. The greater part of the deck on the port side & several shifts on the starboard side have now been renewed.

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulk'ng of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.) When put on	Hawsers & Warps
Top-sides	Clamps & Shelves		Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, Recommendation, &c.:
 Freeboard certificate may now be issued.
 No alteration to be made in date of last survey

Entry Fee (if chargeable) per Scale I, Sec. 27...	£	:	:	Fees applied for, 18/9 18/90 Received by me 18/9 18/90
Office Fee (if chargeable) per Scale II, Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	3	3	
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	
Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

J.C.
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUES 26 AUGUST 1890
 Character assigned Record Freeboard
 TUES. 9 JUN 1891
 Lloyd's Register Foundation
 LON690 - 0350

Form No. 2 for Repairs—1890—21/5/90.—Transfer Ink.—T. & S. J. The Surveyors are requested not to write on or below the space for Committee's Minutes.

Insert Character precisely as in Register Book.