

REPORT of SURVEY for REPAIRS, &c.

No. *222* on the *"HAROLD"* Steel Bk. Master *King*

Date of Writing Report *Sept 5th 1890* Port of *London* Received in London Office *MON 8 SEPT 1890*

No. in Reg. Book *1299* Survey held at *London* Date, First Survey *Aug 6th 1888* Last Survey *Sept 1st 1890*

Built at *Port Glasgow* By whom *R. Duncan & Co* When *1888-3*

Owners *R. T. Stephens & Sons* Port belonging to *London*

Owner's Address *(if not already recorded in Appendix to Register Book.)*

If Surveyed Afloat or in Dry Dock *Dry Dock* Name of Dock *Green's* Destined Voyage *Melbourne*

Length of Poop *ft.:* of Forecastle *ft.:* of Raised Or. Deck *ft.:* Moulded Depth *ft.* ins. Years assigned, if a Wood Ship. Character in Register Book.

Classed *100A1*

Last Survey, No. *8943* Port *Wm. H. H. H.*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship) in Summer *4* ft. *4* ins. in Winter *—* ft. *—* ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Condition*

This vessel was placed in dry dock, the bottom examined cleaned & coated. The windows, having been found defective, new chain lifters were fitted which were equally defective, they were clipped & filled so as to work the cable and again examined & found satisfactory.

PRESENT CONDITION OF THE	Good	Bottom (Bottom) & Counter	Good	Ceiling	Good	Boats	Good
Decks	✓	Transverse Rivets	✓	Rudder	✓	Masts, Yards, &c.	✓
Stairways	✓	Breasthooks and Stemson	✓	Windlass & Capstan	✓	Condition, how ascertained	from L
Upper Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Pumps	✓	Sails	good
Lower Dk. Beams & Fastenings	✓	Timbers of Frame at the opening	✓	Cement (if Iron Ship)	✓	Anchors No. <i>313, 18, 21</i>	good
Keelsons	✓	Plating at other places	✓	Caulking of Bot'm, D'k, & Wat'rways	✓	Cables	good
Deerstrakes	✓	Keelsons	✓	Copper, or Y.M. (State if on Felt.)	—	Hawsers & Warps	✓
Opelides	✓	Clamps & Shells	✓	When put on	—	Standing & Running Rigging	✓
Wales	✓					Hatches	✓
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	✓	Scuppers	good	Cargo & Main Hatchways	good

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel now appears to be in a sound & efficient condition & in my opinion to remain as classed & to have last date of Survey recorded *9/90*

Survey Fee (if chargeable) per Scale I., Sec. 27...	£		
Office Fee (if chargeable) per Scale II., Sec. 27...	£		
Survey Fee (per Section 28)	£	<i>22</i>	
Total on Damage, Fee (if any) (per Sec. 28)	£		
Certificate (if required) to be sent as per margin	£		
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Fees applied for,

Received by me,

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned

SEP 12 1890

100A1