

REPORT of SURVEY for REPAIRS, &c.

No. 51278 Date of Writing Report 4.11.90 18 Port of London Received in London Office THURS 6 NOV 1990
 No. in Survey held at London Date, First Survey 28 Oct- Last Survey 4 Nov- 1890
 381 on the Steel s/s "Northwood" Master J. COOK

TONNAGE:— Built at Newcastle By whom Palmer & Co When 1889
 NET 345 Owners W. France & Co Port belonging to London
 GROSS 718
 UNDER DE. 549 Owner's Address
 (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Name of Dock Union Dock Destined Voyage Looe
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)
 Years assigned, if a Wood Ship. Character in Register Book.

Last Survey, No. 50392 Port London H.M.C. 12. 88
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in Winter ft. ins.
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage.
 Vessel was cut into on Port Side in way of after hatch
 now done, one sheer shake plate renewed and one
 plate in the shake below faired. Two beams in
 way of same faired & replaced. One deck plate
 repaired and one bulwark plate angles and
 mouldings faired & replaced.
 Bottom examined and cleaned and recoated.

PRESENT CONDITION OF THE					
Decks	good	Plank (Bottom) & Counter	good	Ceiling	good
Waterways	"	Treenails or Rivets	"	Rudder	"
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"
Up'r Dk. Beams & Fastenings	"	Transoms, Poles, & Crutches	"	Pumps	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	"	Cement (if Iron Ship)	"
Plank sheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"
Sheerstrakes	"	Keelsons	"	Copper, or Y.M.	"
Topsides	"	Clamps & Shelves	"	(State if on Felt.)	"
Wales	"			When put on	"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"	Scuppers	good
				Cargo & Main Hatchways	good
				Hatches	"

General Observations, Opinion as to Class, Recommendation, &c.:
 This vessel now appears in a good & efficient condition,
 eligible in my opinion to remain as classed and to
 have recorded her date of 11.90

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	18
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:	Received by me,
*Certificate (if required to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute FRI 7 NOV 1990
 Character assigned 100A1

Surveyor to Lloyd's Register of British & Foreign Shipping.
 Robert Edmund Taylor & Son, Commercial Steam Printers, 19, Old Street, Goswell Road, London.

