

REPORT of SURVEY for REPAIRS, &c.

Received in London Office, **WED 12 NOV 1890**

No. 27 Date of Writing Report 27th Oct 18 Port of London
 No. in Reg. Book. 27 Survey held at London Date, First Survey 18 Oct Last Survey 24 Oct 1890
 on the S. S. Jainui Master W. Denny & Bros YEAR. MONTH.

TONNAGE:—

NET 3231

GROSS 5031

UNDER DE. 4131

Built at Dumbarton By whom W. Denny & Bros When 1884 - 9

Owners Shaw Saville & Albion Co Ltd Port belonging to Glasgow

Owner's Address
 (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Victoria Dock Destined Voyage

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (if these particulars are not yet recorded in the Register Book.)

Classed

+100 A1
6.90

Last Survey, No. 50755 Port London SS No 1-88

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials as painted on Ship in Winter ft. ins.
 of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Flooding in No 2 hold over double bottom removed, tank top examined found good & tight under water pressure; recovered with Stockholm tar, cement, & insulation covering of wood with charcoal between.

PRESENT CONDITION OF THE

Decks <u>Good</u>	Plank (Bottom) & Counter	Ceiling <u>Good where seen</u>	Boats <u>Good</u>
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c. <u>"</u>
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained <u>from deck</u>
Up'r Dk. Beams & Fastenings <u>Good</u>	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings <u>where seen</u>	Timbers of Frame at the opening	Cement (if Iron Ship)	Anchors No. of
Plank sheers	Ditto ditto at other places	Caulking of Bottom D'k, & Wat'rways <u>Good</u>	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights <u>Good</u>	Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo & Main Hatchways <u>Good</u>
			Hatches <u>Good</u>


General Observations, Opinion as to Class, Recommendation, &c.: This vessel as far as now seen is in good condition & is in my opinion eligible to remain as classed

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 18 Received by me, 18
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute TUES 18 NOV 1890
 Character assigned 100A1

FEB 20 MAR 1891

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019 Lloyd's Register Foundation
 LON691-0203

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, on.

Insert Character precisely as in Register Book.