

REPORT of SURVEY for REPAIRS, &c.

No. 93 Date of Writing Report Jan 29th 1891 Port of London
 No. in Reg. Book. 93 Survey held at London Date, First Survey Jan 27th Last Survey Jan 29th 1891
 on the S.S. "Malaga" Master J. Russell

TONNAGE:—
 NET 984 Built at Hartlepool By whom M. Gray & Co When 1876 14
 GROSS 1556 Owners J. Hall & Co Port belonging to London

UNDER DEK. 1420 Owners' Address (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Limetiles' Destined Voyage Spain
 Length of Poop ✓ ft.: of Forecastle ✓ ft.: of Raised Or. Deck ✓ ft.: Moulded Depth ✓ ft. ins.

Last Survey, No. 50899 Port Lon Classed Bd 7.90
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter ft. ins.
 of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage
Whilst on a voyage from London to Vigo this vessel took
the ground off Ringis-down on the 26th of December last-
Vessel placed in dry dock, sighted bottom, found
the paint scraped off the bottom (particularly on the
port side), but no other damage was apparent.
The bottom has been cleaned & painted & is now
in good condition.

PRESENT CONDITION OF THE		Plank (Bottom) & Counter	Ceiling	Boats
Decks	<u>Good</u>	Treenails or Rivets	<u>Good</u>	Masts, Yards, &c.
Waterways	<u>"</u>	Breasthooks & Stemson	<u>"</u>	Condition, how ascertained
Comings	<u>"</u>	Transoms, Pointers, & Crutches	<u>"</u>	Sails
Up'r Dk. Beams & Fastenings	<u>"</u>	Timbers of Frame at the openings	<u>"</u>	Anchors No. of
Low'r Dk. Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Cables
Plankbeers	<u>"</u>	Keelsons	<u>"</u>	Hawsers & Warps
Sheerstrakes	<u>"</u>	Clamps & Shells	<u>"</u>	Standing & Running Rigging
Topsides	<u>"</u>	Coal Bunker, Openings, Lids, &c.	<u>"</u>	Hatches
Wales	<u>"</u>	Scuppers	<u>"</u>	Cargo & Main Hatchways
Engine Room Skylights	<u>"</u>		<u>"</u>	

General Observations, Opinion as to Class, Recommendation, &c.:
as far as seen this vessel is now in good
condition, & she is, in my opinion, eligible to remain
as classed, & to have fresh record 1.91 in the reg^r
book

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, <u>29/11 1891</u> Received by me, <u>3/4 1891</u>
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage Fee (if any) (per Sec. 28)	£	2	2	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute TUE 3 FEB 91
 Character assigned 100 A 1
 Ending ---
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 © 2019 Lloyd's Register Foundation