

REPORT of SURVEY for REPAIRS, &c.

52,123

No. 127 Date of Writing Report 18th July 1891 Port of Londonderry Received in London Office, MON. 20 JUL 1891
 No. in Reg. Book 127 Survey held at Lithbury Date, First Survey 9th July Last Survey 17th July 1891
 on the S.S. "Harwarden Castle" (No. of Visits 2) Master R. Duncan

TONNAGE:—
 NET 2669 Built at Glasgow By whom J. Elder & Co. When 1883. 1
 GROSS 4164 Owners Ingold & Currie & Co. Port belonging to London
 UNDER DK 4012 Owners' Address London
 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat in Dry Dock Name of Dock Lithbury Destined Voyage Cape of Good Hope
 Length of Poop 29 ft. : of Forecastle 29 ft. : of Raised Or. Deck 29 ft. : Moulded Depth 10 ft. 0 ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 10810 Port Gls Classed R.S. 550 + L.R.C. 9, 87 100A7
S.S. No 3. Gls 7.91 7.90
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter ft. ins.
 of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR
This vessel has been placed in Graving Dock & the bottom cleaned & coated.
She is reported by Glasgow Report No 10810 to have undergone the No 3 Survey as above.

PRESENT CONDITION OF THE	Good	fair	Good	Good	Good
Decks	Good	Plank (Bottom) & Counter	Good	Ceiling	Good
Waterways	"	Trunnels or Rivets	"	Rudder	"
Comings	"	Breasthooks & Stemson	✓	Windlass & Capstan	"
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	✓	Pumps	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"
Planksheers	✓	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Watrways	"
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.) When put on	✓
Topsides	"	Clamps & Shelves	✓	Boats	Good
Wales	"	Coal Bunker, Openings, Lids, &c	Good	Masts, Yards, &c.	"
Engine Room Skylights	Good	Scuppers	Good	Condition, how ascertained	On Deck
		Cargo & Main Hatchways	Good	Sails	Well found
		Hatches	Good	Anchors No. of	Complete
				Cables	Said to be complete
				Hawsers & Warps	Well found
				Standing & Running Rigging	Good

General Observations, Opinion as to Class, Recommendation, &c. :
This vessel is appearing in good condition in my opinion slight & remain as classed.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 18 Received by me, 18
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 26)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute TUES. 21 JUL 1891
 Character assigned 100A1

no 3 &c

C. Davidson
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 © 2019
 Lloyd's Register Foundation
 Lon 693 - 0355

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent.

Insert Character precisely as in Register Book.

Form No. 2 for Repairs—1000—6/191.—Transfer Ink.—T. & S. (The Surveyors are requested not to write on, or below the space for Committee's Minutes.)