

REPORT of SURVEY for REPAIRS, &c.

No. 286 Date of Writing Report Oct 6th 1891 Port of London
No. in Survey held at London Date, First Survey Oct 5th Last Survey Oct 5th 1891
Reg. Book. (No. of Visits 1)
on the Iron S.S. "Averna" Master A. Tegner.

TONNAGE:— NET 522 GROSS 747 UNDER DK. 355
Built at Sunderland By whom Davison & Co When 1873-9
Owners Pederi Atkie Bol. Avena Port belonging to Uddervalla
Owners' Address (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Com. by S.H. Destined Voyage Uddervalla
Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 37260 Port London
State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer ft. ins.
Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter ft. ins.
of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition. -

This vessel has been placed in dry dock, the bottom examined and found in good order, has been cleaned and re-coated. -

PRESENT CONDITION OF THE		Plank (Bottom) & Counter	Ceiling	Boats
Decks	Good	Good	Good	3. Good
Waterways	"	Turntable or Rivets Parts seen good	Rudder	Masts, Yards, &c.
Comings	"	Breasthooks & Stems Not seen	Windlass & Capstan	Condition, how ascertained From S.H.
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches Parts	Pumps	Sails Stated Good
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the openings seen	Cement (if Iron Ship) Not seen	Anchors No. of 3A. 15. 2K
Planksheers	✓	Ditto ditto at other places Good	Caulk'ng of Bot'm, D'k, & Watrways ✓	Cables Stated complete
Sheerstrakes	Good	Keelsons Good	Copper, or Y.M. ✓	Hawsers & Warps Good
Topsides	"	Clamps & Shelves ✓	(State if on Felt.) ✓	Standing & Running Rigging Good
Wales	"		When put on ✓	Hatches Good
Engine Room Skylights	Good	Coal Bunker, Openings, Lids, &c. Good	Scuppers Good	Cargo & Main Hatchways Good

General Observations, Opinion as to Class, Recommendation, &c. :
The vessel as far as seen appears in good and efficient condition and eligible in my opinion to remain as classed, with further record of survey 10.91.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	18
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	Received by me,
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute 11.13.13 OCT 1891
Character assigned 90A1

P. T. Johnson.
Surveyor to Lloyd's Register of British & Foreign Shipping.

