

REPORT of SURVEY for REPAIRS, &c.

52593

Received in London Office,

5 Jun 92

Date of Writing Report 20 Jun 1892

Port of London

Date, First Survey 8 Dec

Last Survey 11 Decr 1891

Survey held at London

(No. of Visits)

Master Chater

YEAR

MONTH

TONNAGE :-

Built at Newcastle

By whom Palmers & Co

When 1860

10

ET 570

Owners H. James (J. Kuwick Son)

Port belonging to London

ROSS 922

Owners' Address

(if not already recorded in Appendix to Register Book.)

UNDER DK. 846

f Surveyed Afloat or in Dry Dock afloat

Name of Dock

Live Thames

Destined Voyage Lyne

Length of Poop

ft. : of Forecastle

ft. : of Raised Or. Deck

ft. : Moulded Depth

ft. ins.

Years assigned, if a Wood Ship.

Character in Register Book

Classed

+ A#1, 590

Last Survey, No. 52050 Port LON

State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship

in Summer

ft. ins.

in Winter

ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Damage by Collision

On the Port side, one plate in the first stroke below sheer faired in place and one plate in the second stroke below renewed, one frame faired in place. Two side lights repaired. On the Starboard side, one plate in the third stroke below sheer stroke renewed, and one plate in the second and fourth strokes below faired in place, one frame repaired. One breasthook faired in place and one deck floor repaired. Forecastle berths lining is made good.

PRESENT CONDITION OF THE

Decks	good	Plank (Bottom) & Counter	good	Ceiling	good	Boats	good
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"	Condition, how ascertained	Iron Scaff
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	rotten
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors	No. of 35. 15. 2 R
Planksheers	"	Ditto ditto at other places	"	Caulk'ng of Bot'm, D'k, & Wat'rways	"	Cables	rotten
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	good
Topsides	"	Clamps & Shells	"	When put on	"	Standing & Running Rigging	"
Wales	"					Hatches	"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c	"	Scuppers	good	Cargo & Main Hatchways	good

General Observations, Opinion as to Class, Recommendation, &c. : as far as seen this vessel now appears in a good and efficient condition, eligible in my opinion to remain as classed, without fresh record of survey being now made.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 5/11 1892 Received by me 8.1 1892 a.k. 8.1.
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)	£	3	3	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute

Character assigned

FRI 8 JAN 1892

Remains as

Classed

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 10, Old Street, Goswell Road, London.

LON695-0044

dam.

Insert Character precisely as in Register Book.