

REPORT of SURVEY for REPAIRS, &c.

22 MAR 1893

Date of writing Report March 21st 1893 When handed in at Local Office 18 Port of London

No. in Reg. Book 51 Survey held at London Date, First Survey March 14th Last Survey March 17th 1893
on the Wood, Iron or Steel Sc. Sr. "Vauxhall" Master A. W. Wood

TONNAGE:- Built at Newcastle By whom Palmer & Co When 1878 4 MONTH.
GROSS 817 Owners The River Steam Coll. Co. Ltd Port belonging to London
UNDER DK. 762 Owners' Address
NET 528 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Union Destined Voyage Sydney
WB=DBa tons; uE&B tons; Cell DB tons; FPT tons; APT tons; MT tons.

N.B. All alterations in the existing records should be underlined.
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey, No. 28103 Port Nwe
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned or expired. Machinery and Boiler Surveys (including date of N.B., if any).

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs.

The following repairs have been done in consequence of damage stated to have been caused by the vessel colliding with a barge in the River Thames on March 11th 1893.
On Port bow: One plate in T strake renewed, (4th from stem.) one plate in E strake renewed, (3rd from stem) three frames in way of same efficiently repaired.
The vessel's bottom examined & found in good order cleaned down and re-coated.

SUMMARY OF DAMAGE REPAIRS: — Plates, Fair'd or Repaired: 3 Frames, ditto. 2 Plates, Renewed: 1 Frames, ditto. Other Repairs ✓

PRESENT CONDITION OF THE		Parts		Good	
Decks	<u>Good</u>	Transoms, Pointers, & Cleats	<u>Good</u>	Copper, or Y.M. (State if on Felt.)	<u>Good</u>
Waterways	<u>✓</u>	Timbers of Frame at the openings	<u>✓</u>	When put on, Month	<u>Year</u>
Coamings	<u>✓</u>	Ditto ditto at other places	<u>seen</u>	Rudder	<u>Good</u>
Up'r Dk. Beams & Fastenings	<u>Parts seen</u>	Keelsons	<u>Good</u>	Windlass & Capstan	<u>✓</u>
Low'r Dk. Beams & Fastenings	<u>Good</u>	Clamps, Shells & Stringers	<u>Good</u>	Pumps	<u>✓</u>
Plating	<u>Good</u>	Salting (State if examined.)	<u>Good</u>	Engine Room Skylights	<u>✓</u>
Planking	<u>✓</u>	Ceiling	<u>Good</u>	Coal Bunker, Open'gs, Lids, &c.	<u>✓</u>
Treadways	<u>Parts seen</u>	Cement or Asphalt (State which.)	<u>Good</u>	Scuppers	<u>✓</u>
Breasthooks & Stanchions	<u>Good</u>	Tanks (State if now tested.)	<u>✓</u>	Cargo & Main H'tch'w'ys	<u>✓</u>
		Caulking of Bot'm, D'k, & Wat'r'w'ys	<u>✓</u>		
				Hatches	<u>Good</u>
				Boats	<u>3</u>
				Masts, Yards, &c.	<u>From H.R.</u>
				Condition, how ascertained	<u>From H.R.</u>
				Sails	<u>Stated Good</u>
				Equipment letter	<u>✓</u>
				Anchors, No. of	<u>3/13 18 2H</u>
				Cables (State if now ranged)	<u>No</u>
				length	<u>Stated complete</u>
				Rule length	<u>size</u>
				Hawsers & Warps	<u>Good</u>
				Standing & Running Rigging	<u>✓</u>

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

The vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to have record of survey 3.93.

Office Fee (if chargeable) per Scale II., Sec. 27	£	:	:	Fees applied for,
Survey Fee (per Section 29)	£	:	:	18
Special Damage or Repair Fee (if any) (per Sec. 29.)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

*Is Certificate now required? FR 24 MAR 1893
Committee's Minute
Character assigned 90A
Surveyor to Lloyd's Register of British & Foreign Shipping
Lloyd's Register Foundation
lon698-0296