

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 22/10/94 18... When handed in at Local Office 22/10/94... Port of London

No. in Reg. Book 108 Survey held at London Date, First Survey 18/10/94 Last Survey Oct 19 1894

on the Wood, Iron or Steel S. S. Kellie Wise Master R Jackson

TONNAGE:- GROSS 1058 UNDER DK 743 NET 626

Built at W. Northpool By whom Denton, Gray & Co When 1872 12

Owners Green, Holland & Sons Port belonging to London

Owners Address Owners' Address Name of Dock Regent's Dock Destined Voyage

WB=DbA tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.

Years Assigned expired. Machinery and Boiler Surveys (including date of N.B., if any).

6th Survey Hpl 5/93 Society's Freeboard (if assigned) as painted on Ship and now verified

Last Survey, No. 9263 Port Hpl

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repairs on account of damage through collision & grounding.

Now done:- The vessel placed in dry dock, bottom cleaned and examined, several indentations in flat of bottom faired, one bilge plate on port side & one plate on starb'd quarter faired in place, two bulwark plates on starb'd quarter renewed and rail repaired, one boat renewed & fittings repaired.

The bottom rescoated with black varnish, tanks cleaned & examined fore & aft & cement repaired in places. A few rivets in tank girders renewed.

SUMMARY OF DAMAGE REPAIRS: - sand plates, faired or repaired; Frames, ditto. Bulwark plates, renewed; Frames, ditto. Other repairs: a few rivets in tank girders renewed.

PRESENT CONDITION OF THE	
Decks Good	Transoms, Pointers, & Crutches not seen
Waterways "	Timbers of Frame at the openings Good
Coamings "	Ditto ditto at other places "
Up'r Dk. Beams & Fastenings "	Keelsons "
Low'r Dk. Beams & Fastenings "	Clamps, Shells & Stringers "
Plating "	Salting (State if examined.) Good
Planking "	Ceiling "
Treenails or Rivets Good	Cement or Asphalt (State which.) "
Breasthooks & Stems not seen	Tanks (State if now tested.) "
	Caulking of Bot'm, D'k, & Wat'r'w'ys. "
	Copper, or Y.M. (State if on felt.) When put on, Month Year Good
	Rudder Good
	Windlass & Capstan "
	Pumps "
	Engine Room Skylights "
	Coal Bunker, Open'gs, Lids, &c. "
	Scuppers "
	Cargo & Main H'tch'w'ys. "
	Hatches Good
	Boats "
	Masts, Yards, &c. "
	Condition, how ascertained from BK
	Sails Supt
	Equipment letter ✓
	Anchors, No. of 3 B, 1 R + 2 Kgs
	Cables (State if now ranged) Good
	" length size } Supt
	" Rule length size } Supt
	Hawsers & Warps
	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

This vessel is now so far as seen in good condition and in my opinion eligible to remain as classed and to have record of survey 10.94 in the Register Book

Office Fee (if chargeable) per Scale II, Sec. 27	£	Fees applied for,
Survey Fee (per Section 25)	£	18
Special Damage or Repair Fee (if any) (per Sec. 25.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

Committee's Minute Character assigned

FRIDAY 26 OCT 1894

Lloyd's Register Foundation