

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 27th Oct 94 When handed in at Local Office 18 is Port of London

No. in Survey held at London Date, First Survey 13th Oct 94 Last Survey 24th Oct 1894
eg. Book. 741 on the Wood, Iron or Steel John S. Mohawk Master Widshire

TONNAGE:— Built at Belfast By whom Hassland & Wolff When 1892. 5
GROSS 5658 Owners Elder, Dempster & Co Port belonging to London

UNDER DEK. 5278 Owners' Address (if not already recorded in Appendix to Register Book.)
NET 3646

Surveyed Afloat or in Dry Dock? 9. 94 Name of Dock Royal Albert Destined Voyage N. York

WB=DBa tons; f tons; uE&B tons; Cell DB tons;
FPT tons; APT tons; MT tons.

*N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.*

Last Survey, No. 55296 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, &c. for Special Survey, Date of last Survey and of Periodical Surveys.	Year Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
*180 A 1	3.94	
		+2.94. C. 5.94

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage caused by Collision.

Steel and bottom examined in dry dock, and the bottom cleaned and recoated, on the Port bow six shell plates cut out faired and refitted, also one doubling plate in way of same, one bulkhead liner refitted, and the caulking of the collision bulkhead overhauled, twelve frames faired in place, seven reverse bars cut and shifted, and five other reverse bars faired in place, fore and aft bulkhead plate on port side removed, repaired and refitted, several angle lugs connecting lower deck stringer to shell plating removed and refitted, and cement bottom frame spaces renewed.

SUMMARY OF DAMAGE REPAIRS: 7 Plates, Faired or Repaired; 12 Frames, ditto. 1 Plates, Renewed; 1 Frames, ditto. Other Repairs were done by Collision Club

PRESENT CONDITION OF THE		TRANSOMS, POINTERS, & CRUTCHES		COPPER, OR T.M. (State if on Deck.) When put on, Month		HATCHES	
Decks	<u>Good</u>	Timbers of Frame at the openings	<u>Good</u>	Rudder	<u>Good</u>	Boats	<u>Good</u>
Waterways	<u>Good</u>	Ditto ditto at other places	<u>Good</u>	Windlass & Capstan	<u>Good</u>	Masts, Yards, &c.	<u>Good</u>
Coamings	<u>Good</u>	Keelsons	<u>Good</u>	Pumps	<u>Good</u>	Condition, how ascertained	<u>See inside</u>
Up'r Dk. Beams & Fastenings	<u>Good</u>	Clamps, Shelves & Stringers	<u>Good</u>	Engine Room Skylights	<u>Good</u>	Sails	<u>Good</u>
Low'r Dk. Beams & Fastenings	<u>Good</u>	Siding (State if examined.)	<u>Good</u>	Coal Bunker, Open'gs, Lids, &c.	<u>Good</u>	Equipment letter	<u>at</u>
Plating	<u>Good</u>	Ceiling	<u>Good</u>	Scuppers	<u>Good</u>	Anchors, No. of	<u>4. 13. 13. 2. K</u>
Blanking	<u>Good</u>	Cement or Asphalt (State which.)	<u>Good</u>	Cargo & Main H'tch'ys	<u>Good</u>	Chains (State if new ranged)	<u>20</u>
Wascals or Rivets	<u>Good</u>	Tanks (State if now tested.)	<u>Good</u>			length	<u>size</u>
Breasthooks & Stenson	<u>Good</u>	Caulking of Bot'm, D'k, & Wat'r'w'ys	<u>Good</u>			Eye length	<u>size</u>

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of No. 1-91 and ptND91, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed, with records 10. 94.

Office Fee (if chargeable) per Scale II, Sec. 27	Survey Fee (per Section 25)	Special Damage or Repair Fee (if any) (per Sec. 23.)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for,	Received by me,
£	£	£ 4 4 0	£	£	1. 11. 18. 94	28/10/94
					8/12/94	1894

*Is Certificate now required? _____
 Committee's Minute _____
 Character assigned 100A

Form No. 2 for Repairs, 305-5000-10/7/94.—Transfer, Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 *Cerificate, if required, as per Sec. 23.
 *not, state whether, and when, one will be sent.

