

REPORT of SURVEY for REPAIRS, &c.

of writing Report 15th Dec 1894 When handed in at Local Office 18 Port of London

Survey held at London Date, First Survey 3rd Dec Last Survey 13th Dec 1894

Book No. 106 on the Wood, Iron or Steel S.S. "Raphael" Master

TONNAGE:- Built at Glasgow By whom J. Elder & Co. When 1883. 11

GROSS 4202 Owners New Zealand Shipping Co. Ltd Port belonging to London

UNDER DECK 2755 Owners' Address (if not already recorded in Appendix to Register Book.)

NET 2659 Surveyed Afloat or in Dry Dock 9.94 Name of Dock R. Albert Destined Voyage N. Zealand

CB=DBa ✓ tons; f - tons; uE&B ✓ tons; CellDB - tons; FPT - tons; APT - tons; MT - tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 55626 Port Low

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs in account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Hull and bottom examined in dry dock, and the bottom cleared and recoated.

Large blank area for detailed survey notes and repairs.

SUMMARY OF DAMAGE REPAIRS: Plates, Faired or Repaired; Frames, ditto; Plates, Renewed; Frames, ditto; Other Repairs.

PRESENT CONDITION OF THE		Hull		Copper, or V.M.		Hatches	
Decks	Good	Transoms, Pointers, & Crutches	Good	(State if on both)		Boats	Good
Waterways	Good	Timbers of Frame at the openings	Good	When put on, Month	Year	Masts, Yards, &c.	Good
Coamings	Good	Ditto ditto at other places	Good	Rudder	Good	Condition, how ascertained	Survey from 9.94
Up'r Dk. Beams & Fastenings	Good	Keelsons	Good	Windlass & Capstan	Good	Sails	Good
Low'r Dk. Beams & Fastenings	Good	Clamps, Shelves & Stringers	Good	Pumps	Good	Equipment letter	Good
Plating	Good	Salting (State if examined.)	Good	Engine Room Skylights	Good	Anchors, No. of	3 B, 1 S, 2 K
Planing	Good	Ceiling	Good	Coal Bunker, Open'gs, Lids, &c.	Good	Cables (State if now ranged)	Good
Troncons or Rivets	Good	Cement or Asphalt (State which.)	Good	Scuppers	Good	length size	
Breasthooks & Stems	Good	Tanks (State if now tested.)	Good	Cargo & Main H'tch'ys	Good	Rule length size	
		Caulking of Bot'm, D'k, & Wat'r'ys	Good			Hawsers & Warps	Good
						Standing & Running Rigging	Good

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and pEND91, &c."

This vessel is now in good and efficient condition, and eligible to remain as classed with record 12.94.

Office Fee (if chargeable) per Scale II., Sec. 27 £

Survey Fee (per Section 25) £

Special Damage or Repair Fee (if any) (per Sec. 25.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

*Is Certificate now required?

Committee's Minute

Character assigned

100A1 Spar deck

FRI 10 DEC 1894

FRI 10 DEC 1895



© 2019 Lloyd's Register Foundation

LON 704 0087

Vertical text on the left margin: If not, state whether... Certificate, if required, to be sent to... The Surveyors are requested not to write on or below the space for Committee's Minute.