

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 5th April 1895 When handed in at Local Office 18 Port of London

No. in Survey held at London Date, First Survey 6 Mar 1895 Last Survey 5th April 1895  
Reg. Book. on the Wood, Iron or Steel Crown of Denmark Master Milman

1315 TONNAGE:— Built at Dumbarton By whom A. N. Millan & Co When 1883 12

GROSS 2103 Owners Roberton Crimchank & Co Port belonging to Lyle

UNDER DEK 1937 Owners' Address

NET 1987 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Culbertson Destined Voyage San Francisco

WB=DBa tons; f tons; uE&B tons; CellDB tons; } Particulars of Classification (which must be inserted  
FPT tons; APT tons; MT tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 54760 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel's bottom has been examined in dry dock; it is in good condition & has been cleaned & coated. The rudder has been relubricated.

The stock of the starboard lower anchor was broken, & has now been renewed.

The two outer plates on the yard arms of each of the mizzen topsail & fore topsail yards, were wasted thin, & have now been renewed; 4 plates each yard.

SUMMARY OF DAMAGE REPAIRS:—Plates, Fairied or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE Doubling Plates under Sounding Pipes not seen

Decks good Transoms, Pointers, & Crutches " Copper, or I.M. good

Waterways " Timbers of Frame at the openings " (State if on Felt.) Year

Coamings " Ditto ditto at other places " Rudder good

Up'r Dk. Beams & Fastenings not seen Keelsons " Windlass & Capstan "

Low'r Dk. Beams & Fastenings " Clamps, Shelves & Stringers " Pumps not tried

Plating good Salting (State if examined.) " Engine Room Skylights "

Planking " Ceiling " Coal Bunker, Open'gs, Lids, &c. "

Treemails or Rivets " Caulking of Bot'm, D'k, & Wat'rw'ys good Scuppers "

Breasthooks & Stems not seen Hatches good

Boats " Condition, how ascertained good

Masts, Yards, &c. good Sails not seen

Equipment letter W Anchors, No. of 301524

Cables (State if now ranged) no " length size

" Rule length size

Hawsers & Warps good

Standing & Running Rigging "

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

As far as seen this vessel is now in good & efficient condition & is eligible in my opinion to remain as classed with record of survey 4.95

Office Fee (if chargeable) per Scale II., Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 28.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

\*Is Certificate now required? £

Committee's Minute THUR 11 APL 1895

Character assigned 100A1 A1X1

Surveyor to Lloyd's Register of British & Foreign Shipping.

© 2019 Lloyd's Register Foundation

LON 705-0042