

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 16th Oct 1895 When handed in at Local Office 18 Port of London
No. in Reg. Book 1188 Survey held at London Date, First Survey 1st Dec 1894 Last Survey 10th Oct 1895
(No. of Visits 4) Master Harris

on the Wood, Iron or Steel S.S. Doune Castle Built at Sheepen By whom Barclay, Curle & Co When 1890 YEAR MONTH

Owners J. Currie & Co Port belonging to London
Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? in Name of Dock Green Destined Voyage Cape Town

WB=CellDBor.DBa tons; uE&B tons; f tons; FPT tons; APT tons; MT tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 5666 Port London
CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any).

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of S.S. N. 1. - See London Report No. 56661. - Shell and bottom examined in dry dock, and the bottom cleaned and recoated. Ceiling removed on top of H.B. tanks above the after bulk of engine room, and found in good condition, and the ceiling refitted.

SUMMARY OF DAMAGE REPAIRS :-
Plates. Frames. R. Frames. Floors. Beams. Other Items :-
Renewed ...
Faired or Repaired ...
PRESENT CONDITION OF THE
Decks Good
Waterways 7
Coamings 7
Up'r Dk. Beams & Fastenings 7
Low'r Dk. Beams & Fastenings 7
Mast 7
Planking 7
Transoms or Rivets 7
Breasthooks & Stenson 7
Transoms, Pointers, & Crutches 7
Timbers of Frame at the openings Good
Rudder Good
Hatches Good
Boats 7
Masts, Yards, &c. 7
Condition, how ascertained from OK
Sails Good
Equipment letter X
Anchors, No. of 4 B. 15. 1 K
Cables (State if now ranged) no
" length " size "
" Rule length " size "
Hawsers & Warps Good
Standing & Running Rigging 7

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."
This vessel is now in good and efficient condition, and eligible to remain as Classed. and may be marked S.S. 2m 95. with record 10.95.

Office Fee (if chargeable) per Scale II., Sec. 27 £
Survey Fee (per Section 28) £
Special Damage or Repair Fee (if any) (per Sec. 28.) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £
Fees applied for, 18.
Received by me, H. Murray. 18.
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned
TUES. 22 OCT 1895
LLOYD'S REGISTER OF BRITISH & FOREIGN SHIPPING
Lloyd's Register Foundation
LON 706-0467