

FRI. 2 SEP 1898

No.

60232

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of London

No. in Survey held at London Date, First Survey 1st Aug Last Survey 27 Aug. 1898

Reg. Book 332 on the Wood, Iron or Steel BK Ivanhoe (No. of Visits) Master J. G. Brisco

TONNAGE: Built at St. Glasgow By whom J. Reid & Co. When 1868 MONTH 10

GROSS 1402 Owners W. Montgomery Port belonging to London

UNDER DK 1309 Owners' Address

NET 1250 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat 4 in Dry Dock? Name of Dock W. J. Farrer & Co. Destined Voyage Sydney

WB=CellDBorDBa feet; uE&B feet; I feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3373 Port Ant

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition.

Vessel placed in dry dock, bottom sighted, cleaned & re-coated.

Top rudder pintle & gudgeon renewed and lower gudgeons rebushed.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								
PRESENT CONDITION OF THE	Stringers	good	Engine Room Skylights	good	Boats	good		
Decks	Inner Bottom Plating	good	Coal Bunkers, Open'gs, Lids, &c.	good	Masts, Yards, &c.	fm "dk		
Caulking of Decks	State if Tanks now tested	good	Scuppers	good	Condition, how ascertained	(State if wedges removed)		
Waterways	Bulkheads	good	Cargo Hatchways	good	Sails	good		
Coamings	Ceiling	good	Hatches	good	Equipment letter	36, 15, 16		
Beams & Fastenings	Cement or Asphalt (State which.)	good	Planking of Wood Vessels	good	Anchors, No. of	36, 15, 16		
Outside Plating	Rudder	good	Treenails	good	Cables (State if now ranged)	not non		
Caulking of ditto	Windlass	good	Breasthooks & Stemson	good	" length (on board)	18, 15, 16		
Rivets	Have Pumps now been examined and found efficient?	good	Transoms, Pointers, & Crutches ditto	good	" Rule length (per Table 22)	18, 15, 16		
Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	good	Timbers of Frame at openings ditto	good	Hawsers & Warps	good		
Transoms	Have Watertight Doors now been examined and found efficient?	good	Ditto ditto at other places ditto	good	Standing & Running Rigging	good		
Frames	Have Watertight Doors now been examined and found efficient?	good	Stringers, Clamps & Shelves ditto	good				
Reverse Frames	Have Watertight Doors now been examined and found efficient?	good	Salting (State if examined.)	good				
Floors	Have Watertight Doors now been examined and found efficient?	good	Copper, or Y.M. (State if on Fell.)	good				
Keelsons	Have Watertight Doors now been examined and found efficient?	good	When put on, Month	good				
	Dblng. Plates under Sounding Pipes	good		good				

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in good condition and is eligible in my opinion to remain as classed with fresh record of survey 8, 98 Lon.

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,	18
Survey Fee (per Section 28)	£	Received by me,	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£		
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute

Character assigned

TUES. 6 SEP 1898

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

LON716-0289