

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report..... 15..... When handed in at Local Office..... 15..... Port of London
 No. in Survey held at London Date, First Survey Sep 29 Last Survey Oct 11 18 98
 Reg. Book. 1028 on the W. L. Iron or Steel S. Litley Master Hadfield
 TONNAGE:— Built at St. Glasgow By whom Russell & Co. When 1888 MONTH 2
 GROSS 1742 Owners Joley & Co. Port belonging to London
 UNDER DK. 1597 Owners' Address.....
 NET 1672 (if not already recorded in Appendix to Register Book.)
 Surveyed Afloat in Dry Dock? Name of Dock Union Destined Voyage Adelaide

WB=CellDBorDBa feet; uE&B feet; J feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59270 Port Law

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assessed now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100A1</u> <u>10.97</u> <u>SSBNA. N^o 2, 96</u>		✓

Society's Freeboard (if assigned) as painted on Ship and now verified } ..ft.....ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition:

Vessel placed in dry dock, her bottom cleaned
 lighted & re-coated.
 Rudder rebushed.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks <u>Good</u>	Stringers <u>Good</u>	Engine Room Skylights <u>Good</u>	Boats <u>Good</u>
Caulking of Decks <u>do.</u>	Inner Bottom Plating <u>Good</u>	Coal Bunkers, Open'gs, Lids, &c. <u>Good</u>	Masts, Yards, &c. <u>do.</u>
Waterways <u>do.</u>	State if Tanks now tested <u>do.</u>	Scuppers <u>do.</u>	Condition, how ascertained <u>fm deck</u>
Coamings <u>do.</u>	Bulkheads <u>do.</u>	Cargo Hatchways <u>do.</u>	(State if wedges removed)
Beams & Fastenings <u>do.</u>	Ceiling <u>do.</u>	Hatches <u>do.</u>	Sails <u>stated good.</u>
Outside Plating <u>do.</u>	Cement or Asphalt (State which.) <u>do.</u>	Planking of Wood Vessels	Equipment letter <u>u.</u>
Caulking of ditto <u>do.</u>	Rudder <u>do.</u>	Treenails ditto	Anchors, No. of <u>36, 15, 15.</u>
Rivets <u>do.</u>	Windlass	Breasthooks & Stemson ditto	Cables (State if now ranged)
Breasthooks & Crutches	Have Pumps new been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length <u>not run</u>
Transoms <u>do.</u>	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	(on board) <u>ranged.</u>
Frames <u>do.</u>	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" Rule length (per Table 22) <u>good.</u>
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shells ditto	Hawsers & Warps <u>do.</u>
Floors	Have Watertight Doors now been examined and found efficient?	Salting (State if examined.) ditto	Standing & Running Rigging
Keelsons	Dbng. Plates under Sounding Pipes	Copper, or Y.M. (State if on felt.) ditto	
		When put on, Month Year	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in good condition
 eligible in my opinion to remain as classed with
 fresh record of survey 10.98 on.

Office Fee (if chargeable) per Scale II., Sec. 27£
 Survey Fee (per Section 28)£
 Special Damage or Repair Fee (if any)£
 Travelling Expenses (if chargeable)£
 Second Surveyor's Fee (if any)£

Fees applied for,

Received by me,

18.....

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

TUES. 18 OCT 1898

100AY



© 2019

Lloyd's Register
 Foundation

LON 716-0446