

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 27/6/99 When handed in at Local Office 18 Port of London
No. in Survey held at London Date, First Survey 13/6 Last Survey 23/6/1899
Reg. Book. 43 on the Wood, Iron or Steel S.S. Ampule Master
(No. of Visits 2)

TONNAGE:- Built at Sunderland By whom J. L. Ainsie When 1893.
GROSS 2370 Owners Bullard King & Co. Port belonging to London
UNDER DECK 2108 Owners Address
NET 1573 (If not already recorded in Appendix to Register Book.)

Surveyed Afloat in Dry Dock Name of Dock S. J. Ainsie Destined Voyage Natal
WB=CellDBorDBa feet; uE&B feet; I feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* for Special Survey. Date of last Survey and of Periodical Surveys.		
+100A' Spark 7.97		+RM 1.98

Last Report, No. 6122 Port Pau
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition :-

vessel placed in dry dock. bottom sighted. cleaned and recoated with paint. Rudder lifted for examination

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks Good	sd.	good	good.
Caulking of Decks			
Waterways			
Oamings			
Beams & Fastenings			
Outside Plating			
Caulking of ditto			
Rivets			
Breasthooks & Crutches			
Transoms			
Frames			
Reverse Frames			
Floors			
Keelsons			

Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblng. Plates under Sounding Pipes

Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shells	Salting (State if examined.)	Copper, or Y.M. (State if on felt.)	When put on, Month	Year

Boats	Masts, Yards, &c.	Condition, how ascertained	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board)	Rule length (per Table 22)	Hawsers & Warps	Standing & Running Rigging
		from dk	staid sd.	S.	36, 15, 2A	not now ranged.			good	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good condition and is eligible in my opinion to remain as classed with fresh record of survey 6,99 Lon.

Office Fee (if chargeable) per Scale II., Sec. 27	£		Fees applied for,
Survey Fee (per Section 28)	£		18.
Special Damage or Repair Fee (if any) (per Sec. 28.)	£		Received by me,
Travelling Expenses (if chargeable)	£		18.
Second Surveyor's Fee (if any)	£		

D. Martell.
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned TOTAL Spark