

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report
18
When handed in at Local Office
18
Port of London

No. in Reg. Book
129
Survey held at London
Date, First Survey
7
Last Survey
2/8 1899
(No. of Visits)
Master
T. Lilford

On the Wood, Iron, or Steel
S. S. "Ready"
Built at
Middlesbro'
By whom
R. Braggs & Sons
When
1896
Owners
J. Constant
Port belonging to
London
Owners' Address
(if not already recorded in Appendix to Register Book.)

TONNAGE
GROSS
251
UNDER DECK
201
NET
153

Surveyed Afloat or in Dry Dock?
Name of Dock
Limehouse Dry Dock
Destined Voyage

WB=Cold Iron DBa feet; uE&B feet; J feet; }
total capacity tons. FPT 21 tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1895 Port Indle.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned Survey expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A— Coasting 12, 96		12, 96

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

This vessel has been placed in dry dock, and her bottom examined, cleaned and recoated.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks now tested.	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dbng. Plates under Sounding Pipes.
Decks	Good		No	Good			Good					
Caulking of Decks												
Waterways												
Coamings												
Beams & Fastenings												
Outside Plating												
Caulking of ditto												
Rivets												
Breasthooks & Crutches												
Transoms												
Frames												
Reverse Frames												
Floors												
Keelsons												

Engine Room Skylights.	Coal Bunkers, Open'gs, Lids, &c.	Scuppers.	Cargo Hatchways.	Hatches.	Planking of Wood Vessels.	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shelves	Salting (State if examined.)	Copper, or Y.M. (State if on Felt.)	When put on, Month	Year
Good															

Boats.	Masts, Yards, &c.	Condition, how ascertained	Sails	Equipment letter	Anchors, No. of	Cables (State if new or rigged)	" length (on board)	" Rule length (per Table 22)	Hawsers & Warps	Standing & Running Rigging
		(State if wedges removed)								

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 98," or "to remain as classed and to have record of survey, 1, 98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good and efficient condition, and is eligible in my opinion to remain as classed, and to have record of survey, 8, 99, inserted in Register Book.

Office Fee (if chargeable) per Scale II., Sec. 27	£		Fees applied for,	
Survey Fee (per Section 22)	£		18.	
Special Damage or Repair Fee (if any) (per Sec. 25.)	£		Received by me,	
Travelling Expenses (if chargeable)	£		18.	
Second Surveyor's Fee (if any)	£			

Committee's Minute

Character assigned

Thos. Robertson
Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register
Foundation

Lon 719 - 0123