

THUR, 31 AUG 1899

No. 61397

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 18. When handed in at Local Office 18. Port of London  
 No. in Reg. Book. Survey held at Tilbury Date, First Survey and Last Survey Aug 25<sup>th</sup> 1899  
 50 on the Wood, Iron or Steel S.S. "Hakata Maru" Master Lord

TONNAGE:- Built at Glasgow By whom D. & W. Henderson & Co When 1897  
 GROSS 6151 Owners Nippon Yusen Kabushiki Kaisha Port belonging to Tokio  
 UNDER DECK 5495 Owners' Address  
 NET 3814 (If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Tilbury Dry Dock Destined Voyage Japan

WB=Cell DB= DB= 125 feet; u&B 55 feet; f 190 feet;  
 total capacity 1151 tons. FPT 110 tons; APT 37 tons; MT 25 feet 141 tons.

N.B.—All alterations in the existing records should be underlined.  
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. For Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned Survey expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A1 12, 98		LMB 297

Last Report, No. 74 Port Hong Kong

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

This vessel has been placed in dry dock; her bottom examined scraped cleaned and coated.

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	/	/	/	/	/	/	/	/
Removed and Fair'd or Repaired	/	/	/	/	/	/	/	/
Fair'd or Repaired in place	/	/	/	/	/	/	/	/
PRESENT CONDITION OF THE	Good	Good	Good	Good	Good	Good	Good	Good
Decks	Good	Good	Good	Good	Good	Good	Good	Good
Caulking of Decks	/	/	/	/	/	/	/	/
Waterways	/	/	/	/	/	/	/	/
Coamings	/	/	/	/	/	/	/	/
Beams & Fastenings	/	/	/	/	/	/	/	/
Outside Plating	/	/	/	/	/	/	/	/
Caulking of ditto	/	/	/	/	/	/	/	/
Rivets	/	/	/	/	/	/	/	/
Breasthooks & Crutches	/	/	/	/	/	/	/	/
Transoms	/	/	/	/	/	/	/	/
Frames	/	/	/	/	/	/	/	/
Reverse Frames	/	/	/	/	/	/	/	/
Floors	/	/	/	/	/	/	/	/
Keelsons	/	/	/	/	/	/	/	/
Stringers	Good	Good	Good	Good	Good	Good	Good	Good
Inner Bottom Plating	Good	Good	Good	Good	Good	Good	Good	Good
State if Tanks now tested	Good	Good	Good	Good	Good	Good	Good	Good
Bulkheads	Good	Good	Good	Good	Good	Good	Good	Good
Ceiling	/	/	/	/	/	/	/	/
Cement or Asphalt (State which.)	/	/	/	/	/	/	/	/
Rudder	/	/	/	/	/	/	/	/
Windlass	/	/	/	/	/	/	/	/
Have Pumps now been examined and found efficient?	/	/	/	/	/	/	/	/
Have Sluice Valves now been examined and found efficient?	/	/	/	/	/	/	/	/
Have Watertight Doors now been examined and found efficient?	/	/	/	/	/	/	/	/
Dblg. Plates under Sounding Pipes	/	/	/	/	/	/	/	/
Engine Room Skylights	Good	Good	Good	Good	Good	Good	Good	Good
Coal Bunkers, Open'gs, Lids, &c.	/	/	/	/	/	/	/	/
Scuppers	/	/	/	/	/	/	/	/
Cargo Hatchways	/	/	/	/	/	/	/	/
Hatches	/	/	/	/	/	/	/	/
Planking of Wood Vessels	/	/	/	/	/	/	/	/
Treenails ditto	/	/	/	/	/	/	/	/
Breasthooks & Stemson ditto	/	/	/	/	/	/	/	/
Transoms, Pointers, & Crutches ditto	/	/	/	/	/	/	/	/
Timbers of Frame at openings ditto	/	/	/	/	/	/	/	/
Ditto ditto at other places ditto	/	/	/	/	/	/	/	/
Stringers, Clamps & Shells ditto	/	/	/	/	/	/	/	/
Salting (State if examined)	/	/	/	/	/	/	/	/
Copper, or Y.M. (State if on Feet.)	/	/	/	/	/	/	/	/
When out on Month Year	/	/	/	/	/	/	/	/
Boats	Good	Good	Good	Good	Good	Good	Good	Good
Masts, Yards, &c.	/	/	/	/	/	/	/	/
Condition, how ascertained	From deck	From deck	From deck	From deck	From deck	From deck	From deck	From deck
(State if wedges removed)	Good	Good	Good	Good	Good	Good	Good	Good
Sails	Good	Good	Good	Good	Good	Good	Good	Good
Equipment letter	at	at	at	at	at	at	at	at
Anchors, No. of	4 B, 1 S, 1 K	4 B, 1 S, 1 K	4 B, 1 S, 1 K	4 B, 1 S, 1 K	4 B, 1 S, 1 K	4 B, 1 S, 1 K	4 B, 1 S, 1 K	4 B, 1 S, 1 K
Cables (State if now ranged)	Good	Good	Good	Good	Good	Good	Good	Good
" length (on board)	/	/	/	/	/	/	/	/
" Rule length (per Table 22)	/	/	/	/	/	/	/	/
Hawsers & Warps	Good	Good	Good	Good	Good	Good	Good	Good
Standing & Running Rigging	/	/	/	/	/	/	/	/

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptd 98, &c."

This vessel now appears to be in good & efficient condition and is eligible in my opinion to remain as classed & to have record of survey 8, 99 inserted in the Register Book.

Office Fee (if chargeable) per Scale II., Sec. 27

Survey Fee (per Section 25)

Special Damage or Repair Fee (if any) (per Sec. 25.)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

18.

Received by me,

18.

Thos Robertson

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

FRI, 1 SEP 1899

Character assigned

10001



© 2019

Lloyd's Register Foundation

Lon 719 - 0217