

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 22 Oct 99 When handed in at Local Office 18 Port of London
 No. in Reg. Book. 721 Survey held at London Date, First Survey 26th Sep, Last Survey 26th Sep 1899
on the Wood, Iron or Steel 88 "Yusecarora" (No. of Visits) Master

TONNAGE:- Built at Imamuland By whom Mr J Lunn When 1898
 GROSS 6117 Owners FE Bliss Port belonging to London
 UNDER DECK 5649 Owners' Address
 NET 3925 (if not already recorded in Appendix to Register Book.)
 Surveyed Afloat or in Dry Dock Name of Dock Tilbury Destined Voyage
 WB=CellDBorDBa feet; uE&B feet; I feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }
 N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60783 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 CHARACTER.
 * for Special Survey.
 Date of last Survey and of Periodical Surveys.
 Years Assigned expired.
 Machinery and Boiler Surveys (including date of N.B., if any).
 * 100A1
 2.99
 * LMC8.98

Carrying petroleum in bulk.
 Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition

This vessel's bottom has been examined in dry dock cleaned & coated. A new flying bridge has been added

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	good	Stringers	good	Engine Room Skylights	good	Boats	good
Caulking of Decks		Inner Bottom Plating		Coal Bunkers, Open'gs, Lids, &c.		Masts, Yards, &c.	
Waterways		State if Tanks now tested		Scuppers		Condition, how ascertained	from Dk
Coamings		Bulkheads		Cargo Hatchways		(State if wedges removed)	no
Beams & Fastenings		Ceiling		Hatches		Sails	
Outside Plating		Cement or Asphalt (State which)		Planking of Wood Vessels		Equipment letter	at
Caulking of ditto		Rudder	good	Treenails	ditto	Anchors, No. of	6
Rivets		Windlass		Breasthooks & Stemson	ditto	Cables (State if now ranged)	no
Breasthooks & Crutches		Have Pumps now been examined and found efficient?		Transoms, Pointers, & Crutches	ditto	" length (on board)	size
Transoms		Have Sluice Valves now been examined and found efficient?		Timbers of Frame at openings	ditto	" Rule length (per Table 22)	size
Frames		Have Watertight Doors now been examined and found efficient?		Ditto ditto at other places	ditto	Hawsers & Warps	good
Reverse Frames				Stringers, Clamps & Shelves	ditto	Standing & Running Rigging	
Floors				Salting (State if examined.)	ditto		
Keelsons				Copper, or Y.M. (State if on felt.)	ditto		
		Dblg. Plates under Sounding Pipes		When put on, Month	Year		

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good condition & is eligible in my opinion to remain as classed with record of survey 9.99

Office Fee (if chargeable) per Scale II., Sec. 27

Survey Fee (per Section 28)

Special Damage or Repair Fee (if any) (per Sec. 28.)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

18.

Received by me,

18.

Committee's Minute

Character assigned

Alampheer
 Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

10719-0348