

Date of writing Report 27/10/99 When handed in at Local Office 27/10/99 Port of London
No. in Reg. Book. 212 Survey held at London Date, First Survey 24/10/99 Last Survey 26/10/1899
on the Wood, Iron or Steel S/S "Pembroke" Castle Master Marshall

Surveyed Afloat or in Dry Dock *On Wk* Name of Dock *Thames* *h'd* Destined Voyage *Cape*

Particulars of Classification (*which must be inserted precisely as in Register Book & Supplements*).

CHARACTER.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✱ for Special Survey. Date of last Survey and of Periodical Surveys.		

ides ing,	CHARACTER. * For Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100A-1	899	B 8569	+ HMC 1365
the nir the the dent	103.12/95		12/95
	Society's Freeboard (if assigned) as painted on Ship and now verified	 ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *condition*

This steamer was seen lying in the Thames Limited Dry Dock, the bottom examined cleaned and recoated.

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed									
Removed and Paired or Repaired									
Paired or Repaired in place									
PRESENT CONDITION OF THE									
Decks	Good	Stringers	Good	Engine Room Skylights	Good	Boats	Good		
Caulking of Decks	✓	Inner Bottom Plating	✓	Coal Bunkers, Open'gs, Lids, &c.	✓	Masts, Yards, &c.	✓		
Waterways	✓	State if Tanks now tested	✓	Scuppers	✓	Condition, how ascertained	✓		
Coamings	✓	Bulkheads	✓	Cargo Hatchways	✓	(State if wedges removed)	✓		
Beams & Fastenings	✓	Ceiling	✓	Hatches	✓	Sails	✓		
Outside Plating	✓	Cement or Asphalt	✓	Planking	✓	Equipment letter	✓		
Caulking of ditto	✓	(State which.)	✓	of Wood Vessels	✓	Anchors, No. of	✓		
Rivets	✓	Rudder	✓	Treenails	ditto	Cables (State if now ranged)	✓		
Breasthooks & Crutches	✓	Windlass	✓	Breasthooks & Stemson	ditto	" Length	✓		
Transoms	✓	Have Pumps now been examined and found efficient?	✓	Transoms, Pointers, & Crutches	ditto	" Rule length	✓		
Frames	✓	Have Sluice Valves now been examined and found efficient?	✓	Timbers of Frame at openings	ditto	(per Table 22)	✓		
Reverse Frames	✓	Have Watertight Doors now been examined and found efficient?	✓	Ditto ditto at other places	ditto	Hawser & Warps	✓		
Floors	✓	Dblg. Plates under Sounding Pipes	✓	Stringers, Clamps & Shelves	ditto	Standing & Running Riggers	✓		
Keelsons	✓			Salting	ditto				
				(State if examined.)	ditto				
				Copper, or Y.M.	ditto				
				(State if on Felt.)	ditto				
				When put on, Month	Year				

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 198," or "to remain as classed and to have record of survey, 198, and the notations of ss No. 1-98 and pEND98, &c."

This steamer now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed with a good record of survey Nov 1899

Office Fee (if chargeable) per Scale II., Sec. 27	£
Survey Fee (per Section 28)	£
Special Damage or Repair Fee (if any) (per Sec. 28.)	£
Travelling Expenses (if chargeable)	£
Second Surveyor's Fee (if any)	£

Fees applied for

Received by me,

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

TUES. OCT 31 1899

Character assigned

100A

Register of British &

LR

Lloyd's Register
Foundation

Don 719 - 0443