

B.S.
B.S.


Don José de Vega y Flores, public measurer,
^{official surveyor} mechanical engineer, &c., &c.
certifies that by order of the ~~commandant~~^{commissioner} of
this province & harbour master of Havana,
has surveyed the damages caused by fire
to the steam tug Narciso Díazlofen on the
27th August 1894 - The vessel according to
Royal Decrees had been ^{put} ~~detained~~ ~~on the~~
slipway belonging to Mr Lluria —
Surveyed the exterior of the vessel as far as
possible considering the position of the vessel ~~on~~
the slipway: ~~examined~~ all the interior of the
hull, boiler & engines. It was seen that the
fire had completely destroyed the two air tubes,
the chimney of the gallery, the speaking tube
of the telephone & its small chairs, the electric
light installation & accessories, the lead tubes
& a metal cock of one of the water tanks,
the metal ~~balusters~~ of the stairs leading
to the gallery & saloon; also the partitions,
roof & fittings of the gallery, the door of
the ante-chamber (? toilet leading to saloon), the pantry,
the partitions dividing the ante-chamber & the door,
the central partition & flat roof, the door of
the bath room the ladder & ~~balusters~~ ^{but damage} leading to
the ante-chamber —

All these damages have been repaired;
the ~~brasses~~ (~~brasses?~~) of the movements of the engines were
replaced, the shaft levelled by placing new
blocks, — making the whole as good as
before the fire.

All these repairs were finished, surveyed &
approved on the 30th Dec. 1894 & certificate of
navigation given date 1st Jan. 1895

This certificate verified by the Havana authorities, given
to their interest, on the 14th of September 1895. Signed by the surveyor
& Harbour Master.

Printed at
the Office of the
Harbour Master



© 2021
Lloyd's Register
Foundation