

Sent to Chief Surveyor 15.7.95
VESSEL'S NAME Steel S.S. "Benhead"

Received from Chief Surveyor
Report LK No. 7880

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey CLASSIFICATION.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A 1 "Steel" as recommended.

✠ 100 A 1 ("Steel")
1 Dk. (Stl.) 2 trs. Bms.

W B = Cell DB a 66', w E & B 40', f 102' - 417t, APT 50t, FPT 60t.

FK. Cem.

H.M.D.

C. H. J.

15.7.95



© 2019

Lloyd's Register
Foundation

LT4565-0101