

Sent to Chief Surveyor 23.10.93

Received from Chief Surveyor \_\_\_\_\_

VESSEL'S NAME S.S. "Olio" Report Leith No. 7963

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

CLASSIFICATION.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 ("Steel"), "~~Part~~" Awning Deck, with freeboard," as recommended. The Summer freeboard of 8' 5" from centre of disc to top of statutory deck line at ~~part~~ awning deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

100 A 1 ("Steel")

Awning deck with freeboard

1 Stk (Stl) & Awng Stk (Teak).

WB = Cell D.B. a 51' f 102' 187t

FK, cem

WM  
C.H.F. 23.10.95



© 2019

Lloyd's Register  
Foundation

LTH565-0154