

Do. above Crown of }
Engine Room ... }
Gross Tonnage

45.77
2015.23

Girth of Half Mainship Frame (No. 1)
1st Number.....

95.49
305.40

Owners Plate Steamship Co.
Managers G. L. H. Hanky, & Co.

Sent to Chief Surveyor 20.10.96

Received from Chief Surveyor

VESSEL'S NAME S/S 'Oceano'

Report Indb No. 1899

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

Noted
C. A. J.
20/10/96



© 2020

Lloyd's Register
Foundation

MDB755-0171

VEB-FRAMES, In Fore Body, No. and spacing
brdth. & thicknss

15	8	15	8
----	---	----	---

* If Iron or Steel Deck, state if whole or part, and if woc
Number. Thickness. STIFFENING