


s.s. "McFarrel" Nwa Report No. 17407





— SKETCH SHEWING POSITION of Damaged Gudgeon —

& Brace

S.S. No 87

— Scale  $\frac{3}{4}$ " to one foot —



Enlarged view of Gudgeon and Stopper

— Scale 3" inches to one foot —

— No of Lacing 673 —



© 2021

Lloyd's Register  
Foundation