

Sent to Chief Surveyor 5/9/95

Received from Chief Surveyor _____

VESSEL'S NAME

St. S. S. Aureole

Report

RUC

No. 32241

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

Classification

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is worthy to be classed

+ 100 A.1. (Steel) "Spar Sk." "Carrying Petroleum in bulk"—as recommended.

+ 100 A.1. (Stl) "Spar Sk."
"Carrying Petroleum in bulk"
1 Sk (Stl) & Spar Sk (Iron) and Web frames.

W.B. = Cell DB & E & B. 66' 1977 A.P.T. 297 (F.P.T. 1436)
F.K. Cem.



Lloyd's Register
Foundation

NWC843-0056