

SLD933-0026

Size of Bolts in Fastenings, distinguishing whether Copper or Iron; also of Treenails.			Copper Inches.	Iron Inches.
Heel-Knee, and Deadwood abaft	$\frac{1}{18}$	Transoms and throats of Hooks ..	$\frac{1}{18}$	$\frac{1}{18}$
Scarphs of Keel.....N <sup>o</sup> . <i>A</i>	$\frac{1}{16}$	Arms of Hooks .....	$\frac{1}{18}$	$\frac{1}{18}$
Keelson Bolts through Keel at each Floor .....	$\frac{1}{16}$	Bolts thro' Bilge & Limber Strakes, or Thickstuff over Double Floors}	$\frac{3}{4}$	$\frac{3}{4}$
Bolts through Heels of Timbers against Deadwood .....	$\frac{1}{16}$	Butt End Bolts .....	$\frac{1}{16}$	$\frac{1}{16}$
		Pintles of the Rudder .....	$\frac{2}{12}$	$\frac{2}{12}$
		Hold Beam Bolts in {		
		Waterway ..		$\frac{1}{18}$
		Knees .....		$1\frac{1}{18}$
		Shelf or Clamp		$\frac{1}{18}$
		Deck Beam Bolts in {		
		Waterway ..		$\frac{13}{16}$
		Knees .....		$\frac{1}{18}$
		Shelf or Clamp		$\frac{13}{16}$
		Nails or Bolts in Flat of Deck ....		$\frac{13}{16}$
		Treenails $1\frac{1}{4}$ Inches		$5\frac{1}{2}$

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor discoloration and a dark horizontal smudge near the bottom edge. There is no text or other markings on the page.

Her Masts, Yards, &c. are in good condition, and sufficient in size and length.

She has SAILS,		CABLES, &c.		ANCHORS, and their weights.	
N <sup>o</sup> .			Fathoms. Inches.	N <sup>o</sup> .	Weight.
2	Fore Sails,	Chain .....	200 1 7/16	3	15.2.7
1	Fore Top Sails,	Hempen Stream Cable .....	75 8		15.2.0
2	Fore Topmast Stay Sails,	Hawser .....	60 1 1/8	1	15.0.0
1	Main Sails,	Towlines .....	75 5 1/2		4.1.0
2	Main Top Sails,	Warp .....	75 5	1	1
and <u>others as usual</u>		All of <u>good</u> quality.			

Her Standing and Running Rigging is of hemp sufficient in size and good in quality.

She has one Long Boat and two others Eucalypt  
The present state of the Windlass is good Capstan Whinch Rudder good Pumps two Metal

patent General Remarks and Statement and Date of Repairs, if any.

DATES of Surveys held while building, as per Section 35. 1st. When the Frame is completed February 14<sup>th</sup>  
2nd. When the Beams are put in, &c. April 3<sup>d</sup>  
3rd. { When completed, and before the } May 21<sup>st</sup>  
          { plank be painted or payed }

Present condition of Caulking of Bottom, \_\_\_\_\_ Deck, \_\_\_\_\_ and Waterways \_\_\_\_\_

If Sheathed, Doubled, Felted, or Coppered \_\_\_\_\_

I am of opinion this Vessel should be Classed S.A.S.

The Amount of the Fee.....£ 4:- " : " is received by me,

Order No. 5423 Special .....£ 15:- " : "

Sept. 1854 Certificate .....£ - : -

Committee's Minute 2<sup>nd</sup> September 1854

Character assigned \_\_\_\_\_



© 2021

Lloyd's Register  
Foundation