

(wch)

F.E.

by Chief Ship Surveyor \_\_\_\_\_ Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *St. Louis PCM/V ELKHOUND* Rpt. *BN* No. *12282*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee. *94429*

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

*Long*  
Transverse No. *1952.5* Depth "d" *-*

Staging: Table No. *✓* Description *bulk angles as approved.*

Longitudinal No. *7543.75*

Proportions Length *16.13 to upper st.*  
Depth =

~~Deck~~ Sheerstrake *as approved.*

*Revised Rules.*

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to

be classed  
*+ 100 A-1 (Steel) Carrying Petroleum in bulk!  
1 D<sup>x</sup> (Stl)*

*DTf 11' 43E, FPT 46E, APT 40E.*

*FK 10BH. Lloyd's A+C.P. pt Com.*

*P 47', Trunk in well 112', F 18'.*

*mch aft.*

W1000-0035

*W.S.H.*  
*31.10.29*



© 2020

Lloyd's Register Foundation