

No. of Forecastle *2* Transverse Number *100-16* When built *1914* - *1 mo* Launched
 Houses on Deck *590.32* Length on deck from foremast to mainmast
 Workman Clark

Chief Ship Surveyor *J. Z. W.* Received from Chief Ship Surveyor _____

SHIP'S NAME *M/S "Star of Victoria"* Rpt. *Del* No. *7330*
Lin *76359*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Surveyor *Just Entry*


It is submitted the London Surveyors should be requested to state the reason why the survey has not been completed.

M. W. W.

4. 2. 14

to the London Surveyors: -

TK No 4.2.14



Angles on upper edge			
Spacing			
Poop Deck, Angle, Bull Angle, Plate, Poop Bull on Channel	✓ 28	28	
Poop Deck Stringer Plate, breadth & thickness			
Angles on ditto			
Tie Plates			

Dock
 f Deck
 f Tiers
 up of
 Beam,
 Inches
 Spacing
 Ship.
3/4 9-4
9-4
cordi
 Inches
 ip. in Shi
 70
 46
 76
 76
 50
 60
 52
 48
 50
 52