

Do of Forecastle Lower
Houses on Deck

1 68.23
590.32

Transverse Number

100.16

When built 1914 - 1 mo Launched 13

Workman Clark &

ved by Chief Ship Surveyor 2. 2. 14

Received from Chief Ship Surveyor

SEL'S NAME *Sl L.S. "Star of Victoria"* Rpt. *Bel.* No. *7330*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


re of Survey

Irish Entry.

This report should be handed to the London Surveyors for their information and guidance in dealing with the case, and they should be requested to forward a report on Form 8 on the completion of the work in the usual manner with a view to the classification of the vessel.

Lr. 2/2/14

M *W.H.*
2. 2. 14



S, Second, Third & Fourth Deck, Single	10 x 50 x 3 1/2 x 3 1/2 x 50	10 x 3 1/2 x 3 1/2 x 50
Angle Bulb Angle, Plate, Tee Bulb or Channel		
Angles on upper edge		
spacing	28	28
Poop Deck, Angle, Bulb Angle, Plate		

Deck Material and thickness
Poop Deck Stringer Plate, breadth & thickness
Angles on ditto

Dock 12
f Decks w
f Tiers of
up of Up
Beam, Ac
Inches, Spacing in Ship
3/4 9'-4"
9'-4"
cording
es Inches in Ship
70
46
76
76
50
60
52
8
50
52