

F.E.

Received by Chief Ship Surveyor

18/6/12

Received from Chief Ship Surveyor

VESSEL'S NAME

H. I. "Cyclus"

Rpt.

Hue

No. 25107

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

33.86

Depth "d"

11.17

Framing: Table No.

3 page 9

Description

Single angle as approved

Longitudinal No.

4063

Proportions

Length

Depth

9.6

Deck Sheerstrake

50 in run of 34 as required

by the Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100A-1. ("Stub") Steam Trawler as

recommended

$\pm$  100A-1. ("Stub") Steam Trawler

10x

BK 7½' 3BH Gen. Lryds 2060 269



© 2020

Lloyd's Register  
Foundation

W1007-0147