

2 OCT 1944

Rpt. C 11 (a).

NEWCASTLE-ON-TYNE

Lloyd's Register of Shipping.

C/18992


REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship "HOPE STAR" Official Number 161592 Port of Registry NEWCASTLE
Place of Survey NEWCASTLE Dates of Survey 31st Aug 13th & 19th Sept. 1944 Date of last Load Line Survey 21st SEPT. 1943

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs. Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners	good	80 wood covers to renew	19 th Sept. 1944
Beams	good		
Fore and afters	✓		
*Covers	good except.		
*Tarpaulins	good (2)		
(State number per hatchway)			
*Cleats and battens	good		
Lashings and their fittings	good		
Wedges	good (yes)		
(Is supply, including spares, adequate ?)			
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	good		
Beams	✓		
Fore and afters	✓		
*Covers	good		
*Tarpaulins	good (2)		
(State number per hatchway)			
*Cleats and battens	good		
Lashings and their fittings	✓		
Wedges	good. (yes)		
(Is supply, including spares, adequate ?)			
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings	good		
Beams	✓		
Fore and afters	✓		
Covers	good		
Tarpaulins	good (1)		
(State number per hatchway)			
Cleats and Battens	good		
Wedges	good (yes)		
(Is supply, including spares, adequate ?)			
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	good.	5 canvas covers to renew	19 th Sept. 1944
Closing arrangements	good except		
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	✓		
Closing arrangements	✓		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	good.		
7. Within partially enclosed superstructures.			
Closing arrangements	✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	good.		
Skylights, their fastenings, covers and lashings	good.		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	good except	2 door locks to renew.	19 th Sept. 1944
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	good.		

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).



© 2020

Lloyd's Register
Foundation
W1014-0023

(C11^A)

18992.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle	good.		
Bridge, fore end	✓		
Bridge, after end	✓		
Poop	✓		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	✓		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	good.		
17. SIDE SCUTTLES AND DEADLIGHTS			
	good.		
18. GUARD RAILS			
	good		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	✓		
20. LIFELINES (fittings and material)			
	good.		
21. FREEING PORTS.			
Shutters			
Protection bars	Open Rails		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
	✓		
24. LOAD LINE MARKS			
	Verified and found correct.		19 th SEPT. 1944

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined.† († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
all.	H. Little	Newcastle-on-Tyne	19 th September 1944

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor H. Little Place Newcastle-on-Tyne Date 19th September 1944

Signature H. Little
Date 26th September 1944

Fee £5-0-0 TO BE PAID AT
NEWCASTLE ON TYNE

Number of Visits Three
LICENCE CASE

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.